

## PROPELLER MAINTENANCE RECORDS

Aircraft Registration N42 SM
Propeller Position LH
Propeller Serial No. 170495



## **PROPELLER MAINTENANCE RECORDS**

Log No.
Aircraft Registration No. N42 ISM  Propeller Manufacturer McCAULEY  Hub Model 3FF32C5Ø1-D/G9ØUMB-Ø  Blade Design No. 17Ø4-95
1. ALJ 30004 2. ALJ 30005 3. ALJ 30006
Pitch Range:
High Low
Feather Reverse
Governor Manufacturer  Model No  Serial No
Date installed on aircraft
Time Between Overhauls (TBO)Hours
If used on multi-engine aircraft:  ☐ Left ☐ Right ☐ Front ☐ Rear

(All applicable information must be filled in)

Waco Regional Airport • P.O. Box 5219 • Waco, Texas 76708 Phone: (254) 752-8381

Fax: 254-752-3307

www.ramaircraft.com

Page No. DESCRIPTION OF WORK PERFORMED-TOTAL TIME TACH OR TOTAL TIME IN SIGNATURE & CERTIFICATION NO. OF PERSON PERFORMING WORK RECORDING SINCE SERVICE **OVERHAUL** METER TIME PROPELLER ASSEMBLY LOG PAGE NUMBER Aircraft Model Signature & Time Certificate Since Registration Maintenance Total Number Overhaul Number Service History Time Date 1013 3FF320 501-D THIS PROPELLER WAS MANUFACTURED 170495 NEW AT McCAULEY PROPELLER SYSTEMS. INSPECTED AND FOUND TO BE AIR-WORTHY ON THIS DATE.

PROP MODEL (L): 3FF32C501-D PROP S/N (L): 170495 REG. NO: N421SM WORK ORDER: 20170724-1M



Hangar One Avionics

Repair Station No. 1HGR058B 2026 Palomar Airport Road Carlsbad, CA 92011 Phone: 760-929-2270 DATE: 12/12/2017 A/C TSN: 4500 PROP TT (L): 0 HOBBS: 434.1

## **Left Prop Entries**

Completed Annual Inspection IAW FAR 43 Appendix "D" and the Cessna Inspection Time Limits Chart as a guide.

Removed LH propeller: McCauley 3FF32C501A S/N 787692) from N421SM S/N 421C1213, for sublet overhaul. That removed propeller was beyond economical repair and subsequently a new "zero" time propeller assembly was installed with the following customer supplied parts: McCaulley Propeller Model No. 3FF32C501-D/G90UMB-0 S/N 170495 [Blade Serial No's. 1) ALJ30004, 2) ALJ30005, 3) ALJ30006.]

LH Propeller installed with 8ea new MS21044N9 nuts, 8ea P/N A4494 Spacers and 1ea new o-ring P/N A1633-49. Installed 1ea new spinner assembly P/N D5212 (Polished), 1ea new forward spinner support P/N 0855030-3, and as required forward support spacers P/N 0850330-3. Installed 39 ea new stainless spinner screws P/N P/N MS27039C and white phenolic washers. Installed 1ea "Serviceable" unpainted and bead blasted Spinner Bulkhead Assembly P/N D4506. Bulkhead was Alodyne treated, primed and painted with Jetglo Matterhorn White. The existing slip ring was cleaned and installed onto the newly painted bulkhead using 12ea AN503-5-6 drilled-head fillister screws, 12 ea NAS1149CN832R washers and safety wired. Installed 3 ea new deice harnesses P/N 6638, 3 ea new Harness Clamp Blocks P/N E5855-3, 3 ea clamps P/N MS21919WCH6 and assembled wring to bulkhead using 9ea P/N MS21083N06 nuts and the other ends were secured to the propeller blades using 9ea P/N MS21083N06 nuts, 9 ea P/N MS51957-30 screws, 9 ea P/N 7684K-ND insulators and 18ea P/N NAS1149FN632P washers. Wire harness installed in reference to McCauley Propellers C500 Series Full Feathering Maintenance, Overhaul, Parts manual 810915.

Performed Dynamic Balance of LH propeller/engine assembly using the DSS Microvibe II Analyzer. Work performed in accordance with DSS Application note, Document No. AN-MV1-PROP. Permanent balance weights attached to the aft Spinner bulkhead per Chadwick Document No. 9511-2. Final results at 1900 RPM - 0.047 IPS

I certify that this PROPELLER has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition --end--

This aircraft, airframe, or appliance identified above has been repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and Manufacturer data and is approved for return to service.

DATE: 12/12/2017

SIGNED

Work Order: 20170724-1M

Printed by EBis 3 (datcomedia.com)

Mike Clingerman Certified Repair Station No. 1HGR058B