L06B00K # 3 2014 →



ASA-SA-2

Aircraft Record General Information AS OF DEC 2014
Manufacturer Mooney Model M2014 Serial 25-0831 Registration Number N 57645
Serial 25-0831 Registration Number N 57645
Date of Manufacture JULY 1984
Engine(s) currently installed:
Manufacturer CONTINENTAL Model TSIO-360-LB1B Serial 24737-R
Manufacturer $\frac{N/A}{A}$ Model $\frac{N/A}{A}$ Serial $\frac{N/A}{A}$
Propeller(s) currently installed:
Manufacturer NI CAUCY Model 2A34C216B
Manufacturer Mª CAULY Model 2A34C216B HUB Model 490DHB-16E Serial 88214Z Serial N/A
Blade Model #1 Serial IH C76 Serial 72-IH 092 Serial N/A
Blade ModelSerial N/A Serial N/A Serial N/A

14 DEC ALL TIMES TEANSFERRED FROM LOGBOOK # 14 DEC 3204.3 N/A 3843.5 ENGINES/Y 24737-R HAS 1,661.7 HI SINCE FACTORY RE-MAN. I CERTIFY THAT TO AIRCORAFT WAS INSPECTED BY ME I.A.W. AN ANNUAL INSPECTION AND WAS FOUND IN AN AIRW CONDITION. BOTH LANDING LIGHTS REPLACED WITH LED UNITS. LAND, LIGHT LENS FOUND CRUCKED, O REPLACED WITH LENS FABRICATED OF .125" THICK PLEXIGLAS. ELT BATTERY CHANGED, ELT FUNCT CHECK PRE 91.207 SATIS. REPLACED SEVERAL CAM OC FASTENERS IN BELLY SKIN. S. YULLGOT.	ections, Tests, Repairs and Alteration d with Name, Rating and Certificate Number cility. (See back pages for other specific entries)		TOTAL TIME I SERVI	TODAY'S FLIGHT	RECORDING TACK HORBS TIME	YEAR 20 14 Date
SINCE FACTORY RE-MAN. I CERTIFY THAT TO AIRCRAFT WAS INSPECTED BY ME I.A.W. AN ANNUAL INSPECTION AND WAS FOUND IN AN AIRW CONDITION. BOTH LANDING LIGHTS REPLACED WITH LED UNITS. LAND, LIGHT LENS FOUND CRACKED, O REPLACED WITH LENS FABRICATED OF . 125" THICK PLEXIGLAS. ELT BATTERY CHANGED EUT FUNCT CHECK PER 91.207 SATIS. REPLACED SEVERAL CAMOC FASTENERS IN BELLY SKIN. 5. KIWLAGE	FROM LOGBOOK #Z	TE	MES	てい	ALL	4 DEC
SINCE FACTORY RE-MAN. I CERTIFY THAT TO AIRCRAFT WAS INSPECTED BY ME I.A.W. AN ANNUAL INSPECTION AND WAS FOUND IN AN AIRW CONDITION. BOTH LANDING LIGHTS REPLACED WITH LED UNITS. LAND, LIGHT LENS FOUND CRACKED, O REPLACED WITH LENS FABRICATED OF . 125" THICK PLEXIGLAS. ELT BATTERY CHANGED EUT FUNCT CHECK PER 91.207 SATIS. REPLACED SEVERAL CAMPOC FASTENERS IN BELLY SKIN. 5. KIWLAGE						.1.5
SINCE FACTORY RE-MAN. I CERTIFY THAT TO AIRCRAFT WAS INSPECTED BY ME I.A.W. AN ANNUAL INSPECTION AND WAS FOUND IN AN AIRW CONDITION. BOTH LANDING LIGHTS REPLACED WITH LED UNITS. LAND, LIGHT LENS FOUND CRACKED, O REPLACED WITH LENS FABRICATED OF .125" THICK PLEXIGLAS. ELT BATTERY CHANGED EUT FUNCT CHECK PER 91.207 SATIS. REPLACED SEVERAL CAMOC FASTENERS IN BELLY SKIN. 5. KIWLAGE	37-R HAS 1,661.7 HRS	1.5	384	N/A	3204.3	4 DEC
AIRCRAFT WAS INSPECTED BY ME I.A.W. AN ANNUAL INSPECTION AND WAS FOUND IN AN AIRC CONDITION. BOTH LANDING LIGHTS REPLACED WITE LED UNITS, LAND, LIGHT LENS FOUND CRACKED, O REPLACED WITH LENS FABRICATED OF .125" THICK PLEXIGLAS. ELT BATTERY CHANGED ELT FUNCT CHECK PER 91.207 SATIS, REPLACED SEVERAL CAMPOC FASTENERS IN BELLY SKIN. 5. KTULGOR.	- CERTIFY THAT THIS	TO	FA	SINCE		*.
ANNUAL INSPECTION AND WAS FOUND IN AN AIRW CONDITION. BOTH LANDING LIGHTS REPLACED WITH LED UNITS, LAND, LIGHT LENS FOUND CIRCLED, O REPLACED WITH LENS FABRICATED OF .125" THICK PLEXIGLAS. ELT BATTERY CHANGED ELT FUNCT CHECK PRE 91.207 SATIS. REPLACED SEVERAL CAM OC FASTENERS IN BELLY SKIN.	BY ME I.A.W. AN	WAS	AFT	AIR OF		
CONDITION. BOTH LANDING LIGHTS REPLACED WITH LED UNITS. LAND, LIGHT LENS FOUND CRACKED, O REPLACED WITH LENS FABRICATED OF .125" THICK PLEXIGLAS. ELT BATTERY CHANGED EXT FUNCTION CHECK PER 91.207 SATIS. REPLACED SEVERAL CAMPOC FASTENERS IN BELLY SKIN. 5. KITURGER.	AS FOUND IN AN AIRWARTH	INS	AL	ANNY		
LED UNITS. LAND, LIGHT LENS FOUND CRACILED, OR REPLACED WITH LENS FABRICATED OF .125" THICK PLEXIGLAS. ELT BATTERY CHANGED ELT FUNCTION OF CHECK PER 91.207 SATIS. REPLACED SEVERAL CAMOC FASTENERS IN BELLY SKIN. 5. KYWLGOL.	LIGHTS REPLACED WITH	N.	PITT	CONT		
PLEXIGLAS. ELT BATTERY CHANGED EUT FUNCT CHECK PER 91.207 SATIS. REPLACED SEVERAL CAMOC FASTENERS IN BELLY SKIN.						
PLEXIGLAS. ELT BATTERY CHANGED ELT FUNCT CHECK PER 91.207 SATIS. REPLACED SEVERAL CAMPOC FASTENERS IN BELLY SKIN. 5. KYWLGER.	TED OF . 125" THICK	WITT	CED	REDW		
CAMOC FASTENERS IN BELLY SKIN. 5. KYWLGOL.	CHANGED ELT FUNCTION	S.	LIGH	PLEY		
CAMPOC FASTENERS IN BELLY SKIN. 5. KILLIGER.	S. REPLACES SEVERAL	23	uL]	CHE		
5. Krueger	LY SKIN.	15	٥٥	CAM		
LED TOOK SON I	ilger					
	159 工.4.					
2015						2015
6 JAN 3204.6 AD 82-27-03 G/W BY DISASSEMBLY & VISUAL THERECT 6	MBLY & VISUAL TUSPECTED	-03	7-2	AD 8	3204.6	· LAL ·
SEE ENGINE LOG FOR DETAILS	hics	EL	ENGI	SEE		
S. Krueger A€7 1908059						

AR 14/15 TE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
ا د	. Kyu	rege	r Ad	P 1908059
FEB				DUAL NAVI O° NAV2+1° 205° DAG Shawer Hugh
MAY		×		DUAL NAVI & NAV2+10 250 LAS Blown Anglos
MAY	1			REPLACED RIGHT MAIN TIRE WITH RETREAD
-				STD 600-6 TIRE 06-01472 6 PLY.
				OPS CHECK OK, Shamon Hugher
Corp MODEL: S/N: 25-0	0831 D: N5764S DRDER:		Lone Mount Repair Station No. 2830 N. Rancho D Las Vegas, NV 89 Phone: 702-309-2	or. Suite A
The Altim	ne Entries neter, Automatic altit d and found to com	tude reporting, ply with FAR Pa	Static systems, and art 43, Appendix E a	ATC transponder tests and inspections required by FAR 91.411 and 91.413 have been and F.
The aircra	aft and/or componer oproved for return to	nt identified abo service. Pertin	ove was repaired an ent details are on fil	dinspected in accordance with current regulations of the Federal Aviation Administration e at this facility under the above W.O. number.
	3/1/2015	SIGN	1/1	Work Order: AV1378-05-2015
		Ricard Certifi	lo Santiesteban ed Repair Station N	o. L9OR473Y Printed by EBis 3 (datcomedia.com)

YEAR 20 15 DATE 1820N	RECORDING TAON HOBES TIME 3244.6	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries		
	A/C TT	3,88	B.S EN	GINE 3/1 247371R 1,701 SFRM		
	I CE	RTIF	THAT	THIS AIRCRAFT WAS INSPECTED		
	BY ME	工	A.W. A	I ANNUAL IDSPECTION AND WAS,		
	FOUND	IN	AN AL	RNORTHY CONDITION. RETEXETION		
	TEST -	PERFOI	EMEL, G	FAR EXTENDED BY EMERGENCY AND		
	NORMAL		,	ISFACTORY. FLT CHECK SATIL, PER		
	91.20	(, A)	82-2	1-03 YW BY VISUAL INSTEGTION SATIS		
	AD SU	MMIR	CHECK	EL THROUGH 2015-12-06 NONE APPLY.		
				5. Kruener		
				AEP 1908059 I.A.		
	SEE EN	GINE 4	.04 FOR	APPLICABILITY OF A/D 96-12-07		
DATE 08/23/2016 N5764S HOBBS: 3296.2 REMOVED TUBULAR ENGINE MOUNT AND SENT TO AEROSPACE WELDING FOR REPAIR. REINSTALLED TUBULAR MOUNT UPON RECEIPT. INSTALLED A MERLYN PRODUCTS TURBO DIFFERENTIAL PRESSURE CONTROL IN ACCORDANCE WITH STC'S SA4914NM AND SE4731NM. SEE FAA FORMS 337 FILLED OUT AT THIS TIME. MERLYN CONTROL WAS OPS CHECKED WITH ALL INDICATIONS GOODEND.						
BRUCE MCWHORTER A&P 3690658						

TEMR SO	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs Entries must be endorsed with Name, Rating and Ce Technician or Repair Facility. (See back pages for ot	ertificate Number of
	Install	ed engine e installar	e TSIO-360 tion Certific	296.2 TTAF 3935.1 TSMOH 0 -LB1B s/n 247371-R in Mooney M20K N5764 ed Airworthy.	s
	Nore:			ENCED ENGINE INSTALLATION	
				WERHAUL OF REFERENCED ENGIN	NE, DETAILS
				S. Kruey	VEL.
		1		A 47 19080	39

YEAR 20 14 Date	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL A/C TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alteration Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7 OCT	3310.9		3949.8	ENG. 5/N 247371-R 14.7 SMOH, 1768.3 TT
				I CERTIFY THAT THIS AIRCRAFT WAS
				TUSPECTED BY HE I.A.W. AN ANNUAL
				INSPECTION AND WAS FOUND IN AN
				ATRIVORTHY CONDITION. ELT CHECK
		,		PEIZ 91.207 SATISFACTORY, GEAR BETBACT
				EXTEND BY NORMAL & EMERGENCY MEANS
				KATICEN TODY, AN 82-27-03 C/W BY NIS.
				INSP. AD SUMMARY CHECKED THROUGH 2016-19-12, NONE APPLY.
				2016-19-12, NONE APPLY.
				5. Loweger
				5. Voweger A\$P 1308059 I.A.
	. 1		5 2 5 Fe	
55-00-00-00-00-00-00-00-00-00-00-00-00-0				
		1		
	7 7 7 1		180	