

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-C3YF-2UF

PROPELLER S/N EB7062B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position LEFT

Propeller Model PHC-C3YF-2UF

Propeller S/N EB7062B

Blade Design FC7893DFB

Blade S/N's

No. 1 K80463

No. 2 K80466

No. 3 K80469

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather 18.0/81.1

Start Lock N/A

Low 13.0

Reverse N/A

Aircraft Manufacturer CESSNA

Aircraft Model 414

S/N 414-0061

Registration 502JJ

tives,
rections.

Hartzell, PHC-C3YF-2UF, S/N: EB7062B, Hobbs: 0.0 TT: 0.0 SMOH: 0.0 Date: 11/25/09
> Installed new Hartzell propeller (P/N: PHC-C3YF-2UF, S/N: EB7062B) in accordance with RAM STC SA09971SC-D, TIS: 0.0, SMOH: 0.0 on aircraft N502JJ (414, 414-0061) left engine at aircraft total time 4340.0
This propeller is returned to service.
X Justin C. Baker Justin C. Baker IA543081705

N502JJ, Hobbs: 68.5, TSN: 68.5 TSMOH: 68.5 09/16/10
I certify this Propeller has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X Justin C. Baker Justin C. Baker IA543081705

N502JJ BLUE MOUNTAIN AIRCRAFT 11/25/2011
(541) 663-6139
LEFT PROPELLER S/N: EB7062B
TACH: N/A HOBBS: 132.4 TTP: 132.4 SMOH: 132.4
> Complied with an Annual inspection.
I certify this PROPELLER has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X Justin C. Baker Justin C. Baker IA543081705

N502JJ

BLUE MOUNTAIN AIRCRAFT
(541) 663-6139

12/1/2012

LEFT PROPELLER S/N: EB7062B

TACH: N/A HOBBS: 194.2 TTP: 194.2 SMOH: 194.2

> Complied with an Annual inspection.

I certify this **PROPELLER** has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X *Justin C. Baker* Justin C. Baker IA543081705

N502JJ

BLUE MOUNTAIN AIRCRAFT
(541) 663-6139

11/23/2013

LEFT PROPELLER S/N: EB7062B

TACH: N/A HOBBS: ~~192.4~~^{as} 223.4 TTP: ~~192.4~~^{as} 223.4 SMOH: ~~192.4~~ 223.4

> Complied with an Annual inspection.

I certify this **PROPELLER** has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X *Justin C. Baker* Justin C. Baker IA543081705

Date	P TS	<p>N502JJ</p> <p>BLUE MOUNTAIN AIRCRAFT (541) 663-6139</p> <p>LEFT PROPELLER S/N: EB7062B</p> <p>TACH: N/A HOBBS: 266.2 TTP: 266.2 SMOH: 266.2</p> <p>> Complied with an Annual inspection.</p> <p>I certify this PROPELLER has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X <u><i>Justin C. Baker</i></u> Justin C. Baker IA543081705</p>	<p>12/17/2014</p>
		<p>N502JJ</p> <p>BLUE MOUNTAIN AIRCRAFT (541) 663-6139</p> <p>LEFT PROPELLER S/N: EB7062B</p> <p>TACH: N/A HOBBS: 399.9 TTP: 399.9 SMOH: 399.9</p> <p>> Complied with an Annual inspection.</p> <p>I certify this PROPELLER has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X <u><i>Justin C. Baker</i></u> Justin C. Baker IA543081705</p>	<p>12/2/2015</p>

N502JJ

BLUE MOUNTAIN AIRCRAFT
(541) 663-6139

2/17/2017

LEFT PROPELLER S/N: EB7062B

TACH: N/A HOBBS: 511.4 TTP: 511.4 SMOH: 511.4

> Complied with an Annual inspection.

I certify this PROPELLER has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X *JTB* Justin C. Baker IA543081705

1-23-18,	HOBBS: 521.4	I certify THIS PROPELLER HAS BEEN INSPECTED
IAW AN ANNUAL INSPECTION AND HAS BEEN FOUND AIRWORTHY		
		<u><i>JTB</i></u> IA 543081705