

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-C3YF-2UF

PROPELLER S/N EB7059B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position RIGHT

PITCH RANGE

Propeller Model PHC-CY3F-2UF

High/Feather 18.0/81.1

Propeller S/N EB7059B

Start Lock N/A

Blade Design FC7693DFB

Low 13.0

Blade S/N's

Reverse N/A

No. 1 K80475

No. 2 K80782

No. 3 K80478

No. 4 _____

No. 5 _____

No. 6 _____

Aircraft Manufacturer CESSNA

Aircraft Model 414

S/N 414-0061

Registration NS02JJ

Spinner Assembly Part No. _____

Hartzell, PHC-C3YF-2UF, S/N: EB7059B, Hobbs: 0.0 TT: 0.0 SMOH: 0.0 Date: 11/25/09
> Installed new Hartzell propeller (P/N: PHC-C3YF-2UF, S/N: EB7059B) in accordance with RAM STC SA09971SC-D, TIS: 0.0, SMOH: 0.0 on aircraft N502JJ (414, 414-0061) right engine at aircraft total time 4340.0
This propeller is returned to service.
X Justin C. Baker Justin C. Baker IA543081705

atives,
spections.

N502JJ, Hobbs: 68.5, TSN: 68.5 TSMOH: 68.5 09/16/10
I certify this Propeller has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X Justin C. Baker Justin C. Baker IA543081705

N502JJ BLUE MOUNTAIN AIRCRAFT 11/25/2011
(541) 663-6139
RIGHT PROPELLER S/N: EB7059B
TACH: N/A HOBBS: 132.4 TTP: 132.4 SMOH: 132.4
> Complied with an Annual inspection.
I certify this PROPELLER has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X Justin C. Baker Justin C. Baker IA543081705

N502JJ

BLUE MOUNTAIN AIRCRAFT
(541) 663-6139

12/1/2012

RIGHT PROPELLER S/N: EB7059B

TACH: N/A HOBBS: 194.2 TTP: 194.2 SMOH: 194.2

> Complied with an Annual inspection.

I certify this **PROPELLER** has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X *[Signature]* Justin C. Baker IA543081705

N502JJ

BLUE MOUNTAIN AIRCRAFT
(541) 663-6139

11/23/2013

RIGHT PROPELLER S/N: EB7059B

TACH: N/A HOBBS: ~~192.4~~ 223.4 TTP: ~~192.4~~ 223.4 SMOH: ~~192.4~~ 223.4

> Complied with an Annual inspection.

I certify this **PROPELLER** has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X *[Signature]* Justin C. Baker IA543081705

Date	N502JJ	BLUE MOUNTAIN AIRCRAFT (541) 663-6139	12/17/2014
	RIGHT PROPELLER S/N: EB7059B TACH: N/A HOBBS: 266.2 TTP: 266.2 SMOH: 266.2 > Complied with an Annual inspection.		
I certify this PROPELLER has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X <u><i>Justin C. Baker</i></u> Justin C. Baker IA543081705			
Date	N502JJ	BLUE MOUNTAIN AIRCRAFT (541) 663-6139	12/2/2015
	RIGHT PROPELLER S/N: EB7059B TACH: N/A HOBBS: 399.9 TTP: 399.9 SMOH: 399.9 > Complied with an Annual inspection.		
I certify this PROPELLER has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X <u><i>Justin C. Baker</i></u> Justin C. Baker IA543081705			



N502JJ

BLUE MOUNTAIN AIRCRAFT
(541) 663-6139

2/17/2017

RIGHT PROPELLER S/N: EB7059B

TACH: N/A HOBBS: 511.4 TTP: 511.4 SMOH: 511.4

> Complied with an Annual inspection.

I certify this **PROPELLER** has been inspected in accordance with an annual inspection and has been found to be in an airworthy condition. X *JCB* Justin C. Baker IA543081705

1-23-18,	HOBBS: 521.4	I certify THIS PROPELLER HAS BEEN		
		INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION		
		AND HAS BEEN FOUND AIRWORTHY		
		<i>JCB</i> APS43081705 IA		