

N 2015A

Front Rear
Left Right



AMERITECH INDUSTRIES

Exceeding your expectations with every flight™

**20208 Charlanne Drive
Redding, California 96002, U.S.A.
(530) 221-4470 / (800) 292-PROP (7767)**

FAA REPAIR STATION #NO3R717L

E-mail: serviceengine@ameritechind.com



EAGLE ENGINES

A DIVISION OF AMERITECH INDUSTRIES, INC.

ENGINE LOGBOOK

ENGINE MAINTENANCE RECORDS

Log No. _____

Aircraft Registration No. _____

Engine Manufacturer Lycoming

Model ID-360-A1B6

Serial No. L-15657-51A

Date Installed on Aircraft _____

TBO _____ Hours

or _____ Years



DATE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
------	------------------------------	--



2634 Airport Drive # 106 North Las Vegas, NV. 89032 Phone: 702.636.6555 April 20, 2018
 Reg: N201SA S/N: 24-0114 Hobbs: Tach: 4646.25 WO: VGT-3589

Performed engine oil change. Drained old oil and added 8.5 qtrs. of AeroShell W15W-50 oil IAW Mooney M20J Maintenance Manual 12-10-03. Replaced engine oil filter with same P/N CH48110-1 IAW Mooney M20J Maintenance Manual 72-50-00. Performed engine ground run IAW Mooney M20J Maintenance Manual 71-00-40. Leak check good. Satisfactory upon completion. Trouble shot engine oil leak. Found oil filler tube loose. Tightened Oil filler tube IAW Lycoming IO-360-A1B6 Direct Drive Overhaul Manual Section 7. Performed engine ground run IAW Mooney M20J Maintenance Manual 71-00-40. Oil filler tube Leak check good. Satisfactory upon completion.

I certify that the maintenance described above was accomplished in accordance with the Manufacturer's Maintenance Program, requirements of 14 CFR 43, and with respect to the work performed is airworthy and approved for return to service.

Val Sutherland 3641617 A&P *Val Sutherland 3641617 A&P*

2634 Airport Drive # 106 North Las Vegas, NV. 89032 Phone: 702.636.6555 May 16, 2018
 Reg: N201SA S/N: 24-0114 Hobbs: Tach: 4654.48 WO: VGT-3662

Performed engine run, and found leaks at base of oil dip stick tube. Removed oil level gauge gasket, installed new gasket P/N 72059, and performed engine run with satisfactory leak check. Work done in accordance with Lycoming IO-360-A1B6 overhaul manual section 3 page 3-5 paragraph 3-47.

I certify that the maintenance described above was accomplished in accordance with the Manufacturer's Maintenance Program, requirements of 14 CFR 43, and with respect to the work performed is airworthy and approved for return to service.

Bo Bailey A&P 3967496

Bo Bailey



2634 Airport Drive # 106 North Las Vegas, NV. 89032 Phone: 702.636.6555 June 4, 2018
 Reg: N201SA S/N: 24-0114 Tach: 4654.48 WO: VGT-3674

Removed and Replaced Oil Pressure Fitting At right rear AGB. P/N A571-1. Op's and Leak Check Good at this Time. Ref. Lycoming Overhaul Manual P/N 60294-7. Installed missing Camlock, P/N 2753-4 in accordance with Mooney M20J Section 71-12-02 AMM. Satisfactory Upon Completion

I certify that the maintenance described above was accomplished in accordance with the Manufacturer's Maintenance Program, requirements of 14 CFR 43, and with respect to the work performed is airworthy and approved for return to service.

Phillip Swibies 2584811 A&P

Phillip Swibies



2634 Airport Drive # 106 North Las Vegas, NV. 89032 Phone: 702.636.6555 July 13, 2018
 Reg: N201SA S/N: 24-0114 Tach: 4691.46 WO: VGT-3777

Performed engine oil change. Drained old oil and added 8.5 qtrs. of AeroShell W15W-50 oil IAW Mooney M20J Maintenance Manual 12-10-03. Replaced engine oil filter with same P/N CH48110-1 IAW Mooney M20J Maintenance Manual 72-50-00. Performed engine ground run IAW Mooney M20J Maintenance Manual 71-00-40. Leak check good. Satisfactory upon completion.

I certify that the maintenance described above was accomplished in accordance with the Manufacturer's Maintenance Program, requirements of 14 CFR 43, and with respect to the work performed is airworthy and approved for return to service.

Brandon Wood 429696638 A&P *Brandon Wood 429696638 A&P*

