

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL QHC-53YF-1RF/E769Y

PROPELLER S/N FP2392B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model DHC-J34E-1RE/F7694

High/Feather _____

Propeller S/N FP2392B

Start Lock _____

Blade Design 3 B Jade

Low _____

Blade S/N's

Reverse _____

No. 1 J89677

No. 2 J89674

Aircraft Manufacturer Cirrus

No. 3 J89681

Aircraft Model SR22

No. 4 _____

S/N ~~0170~~ 0171

No. 5 _____

Registration N5854A

No. 6 _____

Spinner Assembly Part No. _____

PROP MODEL:
PROP SN:
REG NO: 357E
WORK ORDER: 4660



Lincoln Park Aviation
Repair Station No. LKPR101K
425 Blaevbrook Road
Lincoln Park, NJ 07035
Phone: 973-633-0450

DATE: 7/16/2004
AC TSN: 218.9
PROP TT:
HOBBS: 216.9

Prop Entries

(3) Inspected propeller in accordance with 100 annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 7/16/2004

SIGNED:

Work Order: 4660

Frank R Galella
Certified Repair Station No. LKPR101K

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PROP S/N:
REG. NO. 357E
WORK ORDER: 6468



Lincoln Park Aviation

Repair Station No. LKPR101K
425 Beaverbrook Road
Lincoln Park, NJ 07035
Phone: 973-833-0450

DATE: 7/31/2006
A/C TSN: 468.1
PROP TT: 95.1
HOBBS: 468.1

Prop Entries

(3) ANNUAL/PROP -Inspected propeller in accordance with 100/annual inspection.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 7/31/2006

SIGNED:


Frank R Galella
Certified Repair Station No. LKPR101K

A handwritten signature in black ink, appearing to read 'FRANK R GALELLA', written over a horizontal line.

Inspector 2

Work Order: 6468

Printed by EBis 3 (datamedia.com)

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<p style="text-align: center;">North East Aero 97 Hangar RD Montgomery NY, 12549 (845) 457-1184 Cirrus Design SR22 N357E S/N 0650 Hobbs Time: 581.0 S/N: FP2392B</p> <p>20, October 2007 Hartzell PHC-J3YF-1RF</p> <ol style="list-style-type: none"> 1. Completed Annual Inspection IAW Cirrus Design 100hr/Annual Inspection checklist. 2. Lubricated propeller as required. 3. Dressed blades as required. 4. Inspected spinner with no defects noted. 5. Completed AD list and complied with all outstanding AD's as required. Reference AD list dated 10/07. <p style="text-align: center;"><i>I certify this Propeller was inspected in accordance with an Annual Inspection and found to be in an airworthy condition.</i> Robert C. Betzler 31668811A </p>

North East Aero
97 Hangar RD Montgomery NY, 12549 (845) 457-1184
Cirrus Design SR22 N357E S/N 0650

16, October 2008
Hartzell PHC-J3YF-1N

Hobbs Time: 669.0
S/N: FP2392B

1. Completed Annual Inspection IAW Cirrus Design 100hr/Annual Inspection checklist.
2. Lubricated propeller as required.
3. Dressed blades as required.
4. Completed AD list and complied with all outstanding AD's as required. Reference AD list dated 10/08.

*I certify this Propeller was inspected in accordance with
an Annual Inspection and found to be in an airworthy condition.*

James T. Markey 31668721A

James T. Markey

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP2392B
REG NO: N357E
WORK ORDER:
4865-10-2009



Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 11/5/2009
A/C TSN: 741.7
PROP TT: 741.7
HOBS: 741.7

Prop Entries

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition. Performed prop balance check. Ops checked good.

The aircraft, component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at the facility under the above W O. number.

DATE: 11/5/2009

SIGNED:

Bill Dexheimer

Work Order: 4865-10-2009

Bill Dexheimer
Certified Repair Station No. L9OR473Y

Printed by EBIS 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP2392B
REG. NO: N357E
WORK ORDER:
6525-10-2011



Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 11/10/2011
A/C TSN: 838.5
PROP TT: 838.5
HOBS: 838.5

Prop Entries

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 11/10/2011

SIGNED: 

Bill Dexheimer
Certified Repair Station No. L9OR473Y

Work Order: 6525-10-2011

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP2392B
REG. NO: N357E
WORK ORDER:
7307-11-2012



Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 12/14/2012
A/C TSN: 894.7
PROP TT: 894.7
HOBS: 894.7

Prop Entries

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 12/14/2012



SIGNED: 

James J. Jakus
Certified Repair Station No. L9OR473Y

Work Order: 7307-11-2012

Printed by EBis 3 (datcomedia.com)

**Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.**

Date	Propeller TSN TSO		A/C Hrs		
				 <p>Lone Mountain Aviation, Inc. Repair Station No. L9OR473Y 2830 N. Rancho Dr. Suite A Las Vegas, NV 89130 Phone: (702) 309-2200</p>	
				<p>PROP MODEL: PHC-J3YF-1RF PROP S/N: FP2392B REG. NO: N357E WORK ORDER: 7956-12-2013</p>	
				<p>DATE: 1/12/2014 A/C TSN: 931.3 PROP TT: 931.3 HOBBS: 931.3</p>	
				<p>Prop Entries</p> <p>I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.</p>	
				<p>The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.</p>	
				<p>DATE: 1/12/2014</p>	<p>SIGNED: </p>
				<p>Patrick Harrington Certified Repair Station No. L9OR473Y</p>	<p>Work Order: 7956-12-2013 Printed by EBis 3 (datcomedia.com)</p>

PROP MODEL:
PHC-13YF-1RF
PROP S/N: FP2392B
REG NO: N357E
WORK ORDER:
8879-10-2015



Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 12/10/2015
A/C TSN: 988
PROP TT: 988
HOBBS: 988


Prop Entries

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 12/10/2015

SIGNED:


Kenneth Scheydo
Certified Repair Station No. L9OR473Y

Work Order: 8879-10-2015

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-13YF-1RF
PROP S/N: FP2392B
REG NO: N357E
WORK ORDER:
9003-01-2016



Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 2/2/2016
A/C TSN: 998.7
PROP TT: 998.7
HOBBS: 998.7

Prop Entries

Removed propeller P/N: PC10 TC P36EA S/N: FP2392B for 72 month overhaul.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 2/2/2016

SIGNED:


Sean Yarush
Certified Repair Station No. L9OR473Y

Work Order: 9003-01-2016

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP1627B
REG NO: N5854A
WORK ORDER:
10685-10-2018



Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 11/4/2019
A/C TSN: 1684.6
PROP TT: 1684.6
HOBSBS: 1684.6

Prop Entries

Removed propeller M/N: PHC-J3YF-1RF, S/N: FP1627B (total time 1684.6) and installed overhauled propeller M/N: PHC-J3YF-1RF, S/N: FP2392B (total time 998.7, TSMOH 0.0) and torqued to specs IAW Cirrus SR22 MM 61-10.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 11/4/2019

SIGNED:

Work Order: 10685-10-2018

Travis L. Anderson
Certified Repair Station No. L9OR473Y

Printed by EBIS 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP2392B
REG. NO: N5854A
WORK ORDER:
10683-01-2019



Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 11/4/2019
A/C TSN: 1684.6
PROP TT: 998.7
TSPOH: 0.01
HOBSBS: 1684.6

Prop Entries

I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in airworthy condition.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 11/4/2019

SIGNED:

Work Order: 10683-01-2019

Travis L. Anderson
Certified Repair Station No. L9OR473Y

Printed by EBIS 3 (datcomedia.com)