N 1948B

A Textron Company

ENGINE LOG

SSP-1872-1



652 Oliver Street Williamsport, PA 17701 U.S.A. 570/323-6181

ENGINE LOG AND MAINTENANCE RECORD

RECORD OF _	LYCOMING		TO 360-A1736D	L-21323-51A
, 	MAKE		MODEL	SERIAL
FROM		20	то	20
DETAILING TIME FROM			то	House
		HOURS		HOURS
SSP-1872-	1	© 1994 by Texto	on Lycoming "All Rights Reserved"	October 1994

ENGINE DESCRIPTION

Mfgr.	LYCOMING	Place Williamsport, PA	A 17701 Date
Туре		Model To 360 AIB6	D Serial No. 2-21303-516
Rated H.P.		Max. H.P.	Weight (Dry)
Rated R.P.M		Max. R.P.M.	Oil Pressure
Bore		Stroke	Displacement Cu. In.
Compression Ratio		Supercharger Ratio	
Reduction G	ear Ratio		
Propeller		Hub Design	Hub Serial No.
Blade Desig	n	Blade Serial No.	Blade Serial No.
Max. Hub H.	P.	Max. Blade H.P.	
Pitch		Diameter	Length
Name			
Address			

ENGINE LOG Serial No. Time License Date Signature **REPAIRS - ADJUSTMENTS - SERVICE - REMARKS** Number Hrs Min Installed this engine in 11-21-03 Tach = N1948B Engine Installed with SpanaFlight, Inc. replaced 3715 Meridian E. Bidg. H dated 10-17-63 Puyallup, WA \$83 (253) 848-2020 11-21-03 tach = 3 28.1 has been inspected in accordance with a gond SpanaFlight, Inc. irworthy condition inspection and A& " NO Pionature All Repair Data Must Bear the Endorsement of a Brought Forward Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. Total to Date

LYGUN/ING A Textron Company

652 Oliver Street Williamsport, PA. 17701 U.S.A. TLRED-489 (Rev. 3-02)

--!-! NI-

License Number

This engine has been overhauled/ in accordance with the applicable Lycoming manuals. All applicable Federal Aviation Administration Airworthiness Directives and Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are either new or newly overhauled. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model:

10-360-A1B6D

Serial #:

L-21323-51A

030/03

Total Time: Work Order #:

GJ215010

Date Completed:

3799.25

Lycoming Engines

652 Oliver Street

Authorized Signature

Williamsport, PA 17701 Repair Station: EJ1R115K of a

ENGINE LOG Serial No. License Number Time Signature Date **REPAIRS - ADJUSTMENTS - SERVICE - REMARKS** Min Hrs 11-2/03 actor spersing TACH = Aeroshell 80 eral. Page Total All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. **Brought Forward Total to Date**

EN	CI	N		1	C
	u	IV	L	u	u

Serial No.

Date	Tit	me			Signature	License Number
Date	Hrs	Min	REPAIRS ADJUSTMENTS - SERVICE - REMA	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		
			Cheaves & Gagres Pluos, Che	okes MAG Twick	19.	
			Cleaner Fuel Streens F' F.Z	. NOZZels. de	3.	
			AD 2002-26-01 F.I. Cin	os & Claups.		
			MEXT DUE (B) NEXT NOXLE	/ service		
		Spa	inaflight, Inc. Detetts/o	Total Arcraft Time	42 Se sportiny this	1
	167	15 t	Meridian E. Bldg. H Execute has be unspection and lup, WA 98373 Bigneture	en/inspected in accordant was getermined to be in	airworthy condition	
		Uyal	iup, WA 98373 Eignature	that fare	~ W & W NOODS	مع (هم
		120	(3) 646-2020	•	-0.	
						,
	51 IV 0		Page Total Al	Repair Data Must Bear 1	the Endorsement of a	
			Brought Forward Ce	rtificated Mechanic, and	his Rating and	
			Total to Date	rtificate Number MUST b	e Shown.	

		_	 	-	-	
_		~			_	
-	v		IE		L	
_		_		_	•	•

Serial No.

N1948B



SpanaFlight
16715 MERIDIAN E BLDG H
PUYALLUP, WA 98375
(253) 848-2020



October 10, 2008 TACH: 332.1 TAT: 2748.1 TSMO: 4.0 TSN: 3803.25

Completed an annual inspection this date. Drained and reserviced oil 8qts A/S 80. Replaced CH48104-1 filter and inspected old, ok. Cleaned, gapped and rotated plugs. Cleaned fuel screens. Checked mag timing, ok. Compression tested the cylinders 1-4 the results are as follows: 74, 76. 75 and 75. C/W AD 2002-26-01 by a visual inspection of the fuel injector lines, ok. I certify that this powerplant has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Signature

A&P no GATOMAS JAC

N1948B Entrol in wrong 105 bern see AIL 105 For enlay February 19, 2010 TACH: 332.4 TAT: 2748.4



SpanaFlight
16705 103rd Ave.Ct. E.
PUYALLUP, WA 98374



Completed an annual inspection this date. Wire tied the NLG squat switch wires. Repositioned the flap micro switch wires to clear the A/C's top skin. Reglued a section of the baggage door seal. Replaced the manifold hose under panel with a tube, ops ok. Repaired a broken wire on the throttle gear warning switch. Replaced G35 battery new S/N G02392639. C/W FAR 91.207 by a visual and ops insp, ok. C/W AD76-07-12 by an ops test, ok. C/W AD 87-20-03R2 by a visual, ok. Replaced the Bracket induction air filter element. I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

Signature

A&P no GOYYY235 TA

 Page Total	1
Brought Forward	
 Total to Date	

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

N1948B



SpanaFlight



September 01, 2011 TACH: 332.6 TAT: 2748.6 TSN: 3803.75 TSMO: 4.5 Completed an annual inspection this date. Drained and reserviced oil 8qts. A/S 80. Replaced C1148104-1 filter an internally inspected old, ok Cleaned, gapped and rotated plugs. Cleaned fuel injectors and screen. C/W AD 2008-14-07 by a visual inspection. Checked mag timing, ok. Compression tested the cylinders, the results are as follows 1-4, 72, 77, 75 and 74. Post run, ok. I certify that this powerplant has been

inspected in accordance with an annual inspection and was determined to be in airworthy condition. tto Ut Signature / A&P no 604243955 IA





10-24-2012. N1948B Tach: 332.8 hrs. AFTT: 2748.8 hr Hobbs: 26.7 hrs

1O360-A1B6D. SN: L-21323-51A. TT: 3803.95 hrs. TSO: 4.7 hrs.

Preformed an Annual Inspection in accordance with Cessna and Lycoming maintenance manuals. Replaced oil with 8 qts. shell W80 and filter with new. Compression over 80psi: #1-72. #2-74. #3=78. #4=76. Complied with AD2008-14-07 fuel injection lines. This Engine is in compliance with an Annual Inspection, current Federal Aviation regulations is in an airworthy condition and is returned to service.

Michael Bateman AP36459021A

 1	1	Page Total	All Repair Data Must Bear the Endorsement of a
		Brought Forward	Certificated Mechanic, and his Rating and
 ALL PARTY CONT. ALL PROPERTY CO.	- autorior	Total to Date	Certificate Number MÜST be Shown.

DOBO nber

			ENGINE L	. OG Se	erial No.	
Date	Time Hrs Min	REPAIRS - ADJUST	MENTS - SERVICE -	REMARKS	Signature	License Number
		ies		73Y		
	The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number. DATE: 9/13/2016 SIGNED: Example 4. Work Order: 9292-08-08-08-08-08-08-08-08-08-08-08-08-08-					
		Hubbert, Eri Certified Re		Printed b	by EBis 3 (datcomedia.com)	
		Brought Forward		All Repair Data Must Bear Certificated Mechanic, and Certificate Number MUST	his Rating and	

Above View
FBO
A Professional Oscietion Relation.

Above View Jet Center Inc.

4196 S. Airport Parkway Unit 2A St. George, UT 84790 Phone: 435-688-8009 DATE: 10/13/2016 A/C TSN: ENG TT TACH: 430.9

		A Professional Charlest on Strington.	TACH: 430.9	
Date	Tin	ne Engine Entries		License
	Hrs	M(1) Removed and cleaned #2 fuel injector, reinstalled. Co	mplied with a 50 have	Number
		Maintenance Manual. Replaced oil and filter with a Cham 15W-50 oil. Engine operation checked, no leaks found, or	pion CH 48103-1 filter and 7 star 16	
		15W-50 oil. Engine operation checked, no leaks found.	os check normal.	
	1 1			
		DATE: 10/13/2016 SIGNED:		
		Justin Hansen ARP 3691832	Work Order: 1482	
		AVIATION SERVICES GROUP, LLC. PO Box 910192 St. George, UT 84791 REG #:	4/7/2017 ENG S/N: L-21323-51A	
	\vdash	(435)674-1000/Fax: (435)628-9577 REG #:	N1948B ENG TT: 3943.05	
	├	Thank you for choosing ASGI TACH:	C177RG ENG TSOH: 143.8	
	_	Inspected and serviced in accordance with Cessna Cardinal's 100	Hour Inspection Guide, Channel all and Channel	
		serviced with Aeroshell 15W50 Oil and CH48103-1 Oil Filter. Ch	ecked Compression 1)70/80, 2)76/90, 2)70/90	
	 	4)74/80. Cleaned and Gapped Spark Plugs. Checked timing. C/V ines no defects found. I certify that this engine has been increased.	V AD2011-26-04 by inspection of all find injection	
			cted in accordance with a 100HOLIR INSPECTION	
		and was determined to be in airworthy condition.	3814706 ACPIA	
		Page Total	All Bonois Date March Barrella 5	
		Brought Forward	All Repair Data Must Bear the Endorsement o Certificated Mechanic, and his Rating and	t a
		Total to Date	Certificate Number MUST be Shown.	*

	AVIATION SERVICES GROUP, LLC.	DATE:	9/28/2017	ENG S/N:	L-21323-51A		
	PO Box 910192 St. George, UT 84791	REG #:	N1948B	ENG TT:	3996.05		
	(435)674-1000/Fax: (435)628-9577	MODEL:	C177RG	ENG TSOH:	201.8		
	Thank you for choosing ASG!	TACH:	524.9				License
Date	Inspected and serviced in accordance with Ces	sna Cardinal's 50	Hour Inspection Gui	de. Changed oil a	and filter	ınature	Numbe
Date	serviced with Aeroshell 15W50 Oil and CH481	03-1 Oil Filter. C/V	AD2011-26-04 by i	nspection of all fu	el injection		-
	lines no defects found. I certify that this engi-	ne has been inspe	cted in accordance v	with a 50HOUR IN	SPECTION and		
	was determined to be in airworthy condition.						+
	CFL.						
	Cris Atkin 3394554 A&P						
	onstrum sssassa nar						
					1		
	AVIATION SERVICES GROUP, LLC.	DATE:	8/12/2018	ENG S/N:	L-21323-5	1A	
	PO Box 910192 St. George, UT 84791	REG #:	N1948B	ENG TT:	4061.	65	
	(435)674-1000/Fax: (435)628-9577	MODEL:	C177RG	ENG TSOH	1:26:	2.4	
	Thank you for choosing ASG!	TACH:	590.5				+
	Inspected and serviced in accordance wi	ed oil and filter					
	serviced with Aeroshell 15W50 Oil and 0						
	4)66/80. Cleaned and Gapped Spark Plu	gs. Removed Vacu	um Pump and insta	lled cover plate.	Installed probes a	nd	
	sensors for Electronic Internation CGR 3	•					
	inspection of all fuel injection lines no d			•			
	with a 100HOUR INSPECTION and was d			•	ted in accordance		
	With a 100HOOK INSPECTION and was d	eterrimied to be in	r an worthy conditio	11.			
	1 1	_				nt of a	
	- 1) une /tdone					11.01	•
-	Duane Adams 3814706 A&P IA						

	wo: 15092	,	AND THE STREET CANADA	Engine - page 1 of 1					
Date	Aviation Services Group, LLC · 4196 S Airport Pkwy #52G · St. George, Utah 84790 · (435)674-1000								
	N1948B	Lycoming, IO-360-A18	36D, S/N: L-21323-51A	October 26, 2018					
	Tach: 620.0	TTSN: 4091.15	SMOH: 296.9						
	Aircraft approve	d oil filter in accordance with Ce d for return to service	essna 50 hour inspection. Test	ran and checked for leaks.					
	Brandon Sands	trom A&P 4010810							
	TIT	The state of the s	The state of the s						
		ge Total ught Forward		t Bear the Endorsement of a c, and his Rating and					

FNGINF I OG

Carial Nia

wo: 15244 Engine - page 1 of 2 ense Date mber Aviation Services Group, LLC · 4196 S Airport Pkwy #52G · St. George, Utah 84790 · (435)674-1000 N1948B November 1, 2019 Lycoming, IO-360-A1B6D, S/N: L-21323-51A Tach: 129.2 TTSN: 3600.35 SMOH: -193.9 1. Compression checks: 1. 70/80, 2. 70/80, 3. 75/80, 4. 71/80. 2. Cleaned, gapped and rotated spark plugs. 3. Changed oil and filter. Serviced engine with Aeroshell 15W50 (8 qts) and CH48103-1 filter. 4. Engine run up and leak check. 5. Inspect engine per Cessna 177RG Maintenance manuals 100 hour guide. 6. Inspected fuel lines per AD2011-26-04 no defects found. 7. Adjusted magneto timing to 25 degrees BTC. 8. Removed #2 cylinder fuel injector, ultrasonic cleaned and, Re-installed. 9. Replace oil filter converter gasket. Torqued converter adapter stud to 60 ft lbs. Reinstalled oil filter torqued to 16 ft lbs and safetied. 10. Engine run up and leak check. 1000100000

_	wo: 15	244	A STATE OF THE PARTY OF THE PAR	Engine · p	page 2 of 2	
						License Number
-		Aviation	on Services Group, LLC · 4196 S Airport Pkwy #52G · St. George, Utah 847	790 · (435)674-1000		
-	I certif to be i	y that this engine n an airworthy cor		R INSPECTION and was	found	
-	Dua	Adomo IA 29147	me Lune Alley			
		wo: 15315		Engine - page 1 of 1	,	1
			<u> </u>	Crigina - page 1 or 1		
					l ———	+
_			Aviation Services Group, LLC - 4196 S Airport Plwy #52G - St. George, Utah 84790 - (43	5)674-1000		
_		N1948B Tach: 161.3	Lycoming, IO-360-A1B6D, S/N: L-21323-51A TTSN: 3632.45 SMOH: -161.8	February 11, 2020	ļ	
_		1. Remove cow	vling and drain oil and remove filter.			
_		Added 6 Qua reinstall cow	arts Aeroshell 15 W 50 of and 1 Champion CH48103-1 filter	run up and leak checkand	l ———	+
		Maria	\sim \sim \sim \sim \sim			
_	丁	with respect to the	work performed, this engine is amproved for return to service		rsement of	a
_	\perp	Chris Black A&P 52	28848286		1.	
]	

		EN	GINE LOG	Serial No.			
Date	Time				ns ans		
	wo: 15489		The ARY ON HOUSE THE AREA	Engine - page 1 d	of 1 nb —		
	Aviation Services Group, LLC · 4196 S Airport Pkwy #52G · St. George, Utah 84790 · (435)674-1000						
	N1948B tach: 23		60-A1B6D, S/N: L-21323-5 1 .05 SMOH: 500.8	IA NA October 2 5, 2020 NOV and the) -		
	 Inspect and service per Cessna C177RG Maintenance Manual's 100 Inspection Guide. Clean, gap, and test spark plugs. Drained oil and changed oil filter Installed (1) CH48103-1 - Oil Filter - Spin-On, Installed (8) Qt. Aeroshell 15W50. Checked compression #1 70/80 #2 70/80 #3 72/80 #4 71/80. 						
	I certify that this engine has been inspected in accordance with a 100 HOUR INSPECTION and was determined to be in airworthy condition						
	Duane Adams IA 3814706 Dune Adue						
		Drought Forward	Certificated	Mechanic, and his Rating and			
		Total to Date	Certificate N	umber MUST be Shown.			

wo: 15568	and the same of th	Engine - page 1 of 1	No	
	Awation Services Group, LLC - 4196 S Airport Pkwy #52G - St. George, Utah	.84790 · (435)674-1000	Signature	License Number
stalled (1 2. Change of	Lycoming, IO-360-A1B6D, S/N: L-21323-51A TTSN: 4300.05 SMOH: 500.8 starter and install new starter Installed (1) 149-NL - Sky.) MS25171-3S - Electrical Terminal Nipple - 0.56*x0.43". bil and filter Installed (8) Aeroshell 15W50 oil, Installed (1) the work performed, this engine is approved for return to	-Tec Starter, S/N: H-U111014, In-) CH48103-1 - Oil Filter - Spin-On.		
	Page Total			
	Page Total Brought Forward Total to Date	All Repair Data Must Bear the Certificated Mechanic, and hi Certificate Number MUST be	s Rating and	

			ENGINE L	OG	Seri	al No	
Date	Time	J ,				Signature	License Number
		Date: 11/29/2021 Hours: // Tail#: N1948B	AC: TT: 301.2 EngTT: Prop	T: Hobbs: Misc:			
		Make: Cessna	Model: 177RG	S/N: 177RG0564			
		Run up aircraft. Drained oil an cut open to check for metal pa	rticles. None found. Replaced	d oil filter. Run up and leak			
		checked. Re-installed cowling	and parked aircraft in custom	er hangar.			
		Name: LaDell Bistline Sr.		Cert: AP3273481IA	١.		
		Co: Westwing Aviation	Sign: _<	In Soll Bestless		Endorsement of a Rating and	В

	ENG	INE LOG		Serial No.	
Date: 12/16/2021	Hours: Tach: 301.3; En	gTT: 4363 SMOH: 5	563.	Tail : 1948B	Licen - Numb
Make: Cessna	Model: 17	7RG		S/N: 177RG-0564	
Name: LaDell Bist	ine Sr.	Cert: AP3273481IA			
Co: Westwing	Aviation	Signed:	Tabell	Butting Se.	
	Page Total	All Re	pair Data Must 8	Bear the Endorsement of a	
	Brought Forward Total to Date	Certifi	Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		