
#2



See kew log OH. 8-10-96

MPC-10 Printed in U.S.A. February 1989

Owner Name	
Address	
	B2D34C217-A
Propeller Model _	90 DHB - B
Blade Model	
Hub Serial No	792452
Blade Serial No. 1	B107282
2	B107344
3	
4	

INSTALLATION HISTORY

Aircraft Model & Registration No.		Engine Serial Number & Position
CESSNA TR182	N756RW	1-21519-40A
		,

MAINTENANCE & SERVICE HISTORY

nd Station	Authorized Signatur Repairman and Station Certificate Number	Description Of Work	Time Since Overhaul	Total Propeller Time	Date
pec	overhoused pec	Propellee completely ou	Ø		1/10/89
ice	. All Service	manufactuees spees.	•		
res	ting A.D. Notes	Le Hees, Seevice Billotin			
-	· .	a/w To this date			
·llee	+ Coast Peopellee				
Acific	of Howker Pacific	du of			
75	PAUR Sta 4275	Repay			
Ca	12 Valley Ca	Sun			
	MIMIC				
6687	2346687				
(Unlley (Sulva Sable FAA A.D. & Factory Service Bul	ce With All Applic	Enter Complian	NOTE:

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
	I certify tha accordance wi to be in airw	1990 N 756RW t this Propelle th an annual in prthy condition RS #401-225	er has been inspected in nspection and was found	E BLVD
NOTE	Enter Complian	oo Wish All Assati	cable FAA A.D. & Factory Service Bull	

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
5-27-94	1. 0.		PROPORER DypAnicall	y BALANCOO
3-21-1-	2010		AT YOUR HIGH P.PM.	J. I IPS IAW
			CHADWICK HELLWIH BO	Jances.
				APPS62619541
24-95	2388		PROSS PROPOllop withs	Hand States
			PROSS PROBILOR NINS	BN 479503 TA
NOTE:	Enter Complian	nce With All Appli	cable FAA A.D. & Factory Service Bul	letins On Pages 11 & 12

SANTA MONICA PROPELLER INC

3025 AIRPORT AVENUE SANTA MONICA CALIFORNIA 90405-6186



FAA REPAIR STATION 4015 TELEX 182028 M PROP SNM (213) 390-6233

SERVICEABLE PARTS TAG

CUSTOMER VAN NUMS SKYWAYS W.O. NO. 20600 GOZDATE 1-10.90
MODEL NO. C290 D3E/T21 DESCRIPTION MC COULEY CONEYNO
SERIAL NO. 791280 QUANTITY 4
Completely Overhauled
Part Repaired Only New Electric Deice Installed . Blades Penetrant Insp., Anodized
Blade Damage Repaired
Hub Exchanged w/OHC Unit AD, SB Compliance Only Blades Edge Trimmed & Painted
REMARKS

SEE REVERSE FOR AUTHORIZATION

CALIFORNIA PROPELLER NORTH HOLLYWOOD, CALIFORNIA

SERV		

W.O. NO. PART NO. C 27 00 3-76/13
CUSTOMER THOMOSON AIRCRAFT CORP. P.O. NO. 4722
SERIAL NO. 79/280 MODEL C 290 D 3- E/721
DESCRIPTION PROP GOU ASSY - Me Caulay
OVERHAULED & CERTIFIED
MAIN OVERHAUL MANUAL # 78040/
INSPECTOR 2253721 COP
SIGNED
3-1-52

AIRWORTHINESS RELEASE

756RW

The component identified on the face of this tag was repaired and inspected in accordance with current F.A.A. Regulations and was found airworthy for return to service.

Pertinent details of the repair are on file at this agency.

Date 3-1-53

Signed Del Delaman

AUTHORIZED SIGNATURE

CALIFORNIA PROPELLER
8101 LANKERSHIM BLVD.
NORTH HOLLYWOOD, CALIFORNIA

F.A.A. APPROVED REPAIR STATION NO. AZ4R068M

SANTA MONICA PROPELLER INC

3025 AIRPORT AVENUE SANTA MONICA CALIFORNIA 90405-6186

Hub Exchanged w/New Unit



FAA REPAIR STATION 4015 TELEX 182028 M PROP SNM (213) 390-6233

Propeller Assembled, Lubricated, Balanced.

LTD W.O. NO. 20598/-1815 MODEL NO. BAD34021 DESCRIPTION MCCaule SERIAL NO. 792452 QUANTITY Completely Overhauled Angles Corrected Steel Parts Magnafluxed & Cadmium Plated AD's, SB's, SL's Incorporated New Blades Installed □ Aluminum Hub Penetrant Insp., Anodized New Electric Deice Installed . Part Repaired Only Blades Penetrant Insp., Anodized →New Seals Installed Only 🛛 New Alcohol Deice Installed . Blades Penetrant Insp., Alodined. . Blade Damage Repaired □ Parts Inspected Only Blade Shanks Compression Rolled. AD, SB Compliance Only Hub Exchanged w/OHC Unit □ Blades Edge Trimmed & Painted

Propeller disassembled cleaned and inspected. SB135 C/W

Governor RPM Tested & Set



SERVICEABLE				
Part No. B2D34C217-A Ser. No.	792452			
Part Name MCCAuley Peopellee	Assy			
Customer VAN Nyys Skyways Date 1	1-10-89			
The Aircraft and/or Component identified above was repaired an				

The Aircraft and/or Component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency under Work Statement

Work Order #	P0359	P.O. #	

Flight Accessory Services

a Division of

Hawker Pacific, Inc.

11310 Sherman Way • Sun Valley, CA 91352

FAA APPROVED REPAIR STATION NO. 4275

□ INSPECTE	ED ONL
VERHAL	JLED
REPAIRED	_
MODIFIED)

LY CONTINUE TIME

ZERO TIME

TO CUSTOMER'S
INSTRUCTIONS

SEE REVERSE

TESTED ONLY

URE 12///17

024-1