

*Executive Propellers*  
*inc.*

#3

16140 COVELLO STREET • VAN NUYS, CALIFORNIA 91406

**(818) 779-7767 • FAX (818) 779-0848**

*FAA CRS # EU6R595N*



**PROPELLER LOGBOOK**

### PROPELLER MAINTENANCE RECORD

Propeller Manufacturer: McCauley

Hub Model No. B2034C217.A

Hub Serial No. 792452

Blade Model No. 90 DHB-8

Blade Serial No. 1 B107282

No. 2 B107334

No. 3 \_\_\_\_\_

No. 4 h h

No. 5 \_\_\_\_\_

#### PITCH RANGE

High 32° Low 15.8° Feather ~~~~ Reverse ~~~~

Governor Manufacturer: \_\_\_\_\_

Governor Model No. \_\_\_\_\_

Governor Serial No. \_\_\_\_\_

Maximum Hours or Service Life between overhaul recommended by Mfg. 2000 Hrs. or Six


years, whichever occurs first.

### CUSTODY RECORD

Owner	Date Rec'd.
Owner	Date Rec'd.
Owner	Date Rec'd.
Owner	Date Rec'd.

	Make/Model	Serial #
<b>Aircraft Installed On:</b>		

### OVERHAUL RECORD

No.	Date	Repair Station and No.	Signature
	2-13-2002	<i>Executive Propellers, Inc.</i> 16140 Covello St., Van Nuys, CA FAA CRS # EU6R595N	

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		<b>PROPELLER COMPLETELY OVERHAULED. I.A.W.</b>	
		McCAULEY SERVICE MANUAL # <u>180630, SPM100-1</u> , BOM100-1	
		ALL A.D.'s AND McCAULEY S.B.'s AND S.L.'s	
2-13-2002	"0"	COMPLIED WITH TO DATE. <i>Detinent details of this overhaul</i>	
	S.P.O.H.	<i>are on file under W.O. 02-045 at the following facility:</i>	
		<b>Executive Propellers, Inc.</b>	
		16140 Covello St., Van Nuys, CA	
		FAA CRS # EU6R595N	<i>James Salvi</i>
3/26/02	2765.1	installed on R-192 N 756 RW	
		<i>Whitaker O/P 1455047</i>	
5-01-2003	2793	inspected per ANNUAL INSPECTION REPORT SERVICES	
		<i>John S. Lopez AT 11795003</i>	

MANUFACTURER McCawley  
MODEL B2034C217.A  
SERIAL NO. 792452  
BLADE MODEL 90 DHB-8  
BLADE SER. NO. B107282, B107334.

---

### MAINTENANCE RELEASE

The propeller part identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Agency and was found to be air-worthy with respect to the work performed and is approved for return to service. Pertinent details of the repair are on file at this Repair Station under

02-045

zygloed, alumined, painted and balanced. Magnafluxed all steel parts, zygloed all aluminum parts. Cad plated where required. Parts replaced where required, propeller assembled, lubricated and balanced. Functionally tested, angles set to Mfgs. specs.

15.8° LOW PITCH

32° HIGH PITCH

SERVICE BULLETINS 106, 119A, 145, 146  
and 146-2 all reviewed and  
complied with.

SERVICE LETTERS 79-5, 79-7, 87-3,  
98-5, 98-23 all reviewed

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

PROP MODEL  
B2034C217-A  
PROP S/N 792452  
REG NO. N756RW  
WORK ORDER  
1825-08-2004

**Ron's Aircraft Service, Inc.**

Repair Station No. RJUR641K  
2810 Perimeter Road, Suite 101  
North Las Vegas, NV 89032  
Phone: 702-646-6191

DATE 6/16/2004  
A/C TSN 2904 2  
PROP TT  
TSPON 139 1  
TACH 2904 2

**Prop Entries**

This Propeller has been inspected as part of an Annual/100 hour inspection and was found to be in airworthy condition

DATE 6/16/2004

SIGNED



Work Order 1825-08-2004

Printed by EBis 3 (datcomedia.com)

PROP MODEL  
B2034C217-A  
PROP S/N 792452  
REG NO. N756RW  
WORK ORDER  
2862-09-2005

**Ron's Aircraft Service, Inc.**

Repair Station No. RJUR641K  
2810 Perimeter Road, Suite 101  
North Las Vegas, NV 89032  
Phone: 702-646-6191

DATE 9/16/2005  
A/C TSN 2949 7  
PROP TT 45.5  
TSPON 184.6  
TACH 2949 7


**Prop Entries**

This Propeller has been inspected as part of an Annual/100 hour inspection and was found to be in airworthy condition

The aircraft and/or component(s) on N756RW was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Further details of the repair are on file at this repair station under Work Order No. 2862-09-2005

DATE: 9/16/2005

SIGNED:



Work Order: 2862-09-2005

Printed by EBis 3 (datcomedia.com)

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

PROP MODEL:  
B2D34C217-A  
PROP S/N: 792452  
REG. NO: N756RW  
WORK ORDER:  
3873-01-2007

Ron's Aircraft Service, Inc.

Repair Station No. RJUR641K  
2810 Perimeter Road, Suite 101  
North Las Vegas, NV 89032  
Phone: 702-646-6191

DATE: 2/13/2007  
A/C TSN: 3032.5  
PROP TT: 128.3  
TSPOH: 267.4  
TACH: 3032.5

Prop Entries

This Propeller has been inspected as part of an Annual/100 hour inspection and was found to be in airworthy condition.

This aircraft N756RW and/or its component(s) was repaired or inspected in accordance with current Federal Aviation Regulations and was found Airworthy, and is approved for return to service. \*Pertinent details of the work performed are on file at this repair station under Work Order No. 3873-01-2007

DATE: 2/13/2007

SIGNED




Work Order: 3873-01-2007

Printed by EBis 3 (datcomedia.com)

**HORTON AVIATION SERVICES**  
**2732 PERIMETER ROAD, SUITE 101**  
**NORTH LAS VEGAS, NEVADA 89032**

**N# N756RW MFG. CESSNA MODEL TR182 S/N R18201142\_W.O. # 08-79**  
**PROPELLER: PSO: 320.9**

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.

  
AB4542780472A



DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

DESCRIPTION OF WORK	SIGNATURE
<p>HORTON AVIATION SERVICES LLC FAA CRS YHSR-284L 2732 PERIMETER ROAD, SUITE 101 N. LAS VEGAS NV 89032</p> <p><u>N# N756RW MFG.CESSNA MODEL TR182 S/N R18201142 W.O. 09-022 DATE 05/01/2009 TACH. 3140.0</u></p> <p>I certify that this propeller has been inspected I/A/W an annual inspection and found to be in an airworthy condition.</p> <p><i>Chat</i></p>	

DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS

HORTON AVIATION SERVICES LLC  
FAA CRS YHSR-284L  
2732 PERIMETER ROAD, SUITE 101  
N. LAS VEGAS NV 89032

N# N756RW MFG.CESSNA MODEL TR182 S/N R18201142 W.O, 09-246 DATE 10/15/2009 TACH. 3169.4  
PROPELLAR: MODEL B2D34C217-A S/N 792452  
A/C TSN: 3169.4 PROP TT: 265.2 TSPOPH: 404.3 TACH: 3169.4

I certify that this propeller has been inspected I/AW an annual inspection and found to be in an airworthy condition.

The aircraft and/or component above were repaired and inspected in accordance with Federal Aviation Regulations and are approved for return to service. Pertinent details are on file at this agency under above work order number. APPROVED FOR RETURN TO SERVICE.







HORTON AVIATION SERVICES LLC  
FAA CRS YHSR-284L  
2732 PERIMETER ROAD, SUITE 101  
N. LAS VEGAS NV 89032

N# N756RW MFG.CESSNA MODEL TR182 S/N R18201142 W.O. 12-104 DATE 04/02/2012 TACH. 3382.61


I certify that this propeller has been inspected I/A/W an annual inspection and found to be in an airworthy condition.

The aircraft and/or component above were repaired and inspected in accordance with Federal Aviation Regulations and are approved for return to service. Pertinent details are on file at this agency under above work order number. APPROVED FOR RETURN TO SERVICE 

HORTON AVIATION SERVICES LLC  
FAA CRS YHSR-284L  
2732 PERIMETER ROAD, SUITE 101  
N. LAS VEGAS NV 89032

N# N756RW MFG.CESSNA MODEL TR182 S/N R18201142  
W.O. 13-113 DATE 5/3/2013 TACH. 3518.18


I certify that this propeller has been inspected I/A/W an annual inspection and found to be in an airworthy condition.

The aircraft and/or component above were repaired and inspected in accordance with Federal Aviation Regulations and are approved for return to service. Pertinent details are on file at this agency under above work order number. APPROVED FOR RETURN TO SERVICE 

HORTON AVIATION SERVICES LLC  
FAA CRS YHSR-284L  
2732 PERIMETER ROAD, SUITE 101  
N. LAS VEGAS NV 89032

N# N756RW MFG.CESSNA MODEL TR182 S/N R18201142  
W.O. 14-110 DATE 6/12/2014 TACH. 3618.79


I certify that this propeller has been inspected I/A/W an annual inspection and found to be in an airworthy condition.

The aircraft and/or component above were repaired and inspected in accordance with Federal Aviation Regulations and are approved for return to service. Pertinent details are on file at this agency under above work order number. APPROVED FOR RETURN TO SERVICE 





# FAA AIRWORTHINESS DIRECTIVES COMPLIANCE RECORD

Year: <u>2002</u>	Total Hours	Complied by the following:  <div style="font-family: cursive; font-size: 1.2em; text-align: center;">                     Blade serial numbers B107282 and B107334                      are not applicable to this Airworthiness                      Directive - No further action required.                 </div>
Date: <u>2/13</u>		
A.D. #  <u>82-27-02R1</u>		
Next Inspection Due:  <u>at overhaul</u>		
		Signature: <u></u>

**Executive Propellers, Inc.**  
 16140 Covello St., Van Nuys, CA  
 FAA CRS # EU6R595N

Year: _____	Total Hours	Complied by the following:  <div style="font-size: 0.9em;"> <b>HORTON AVIATION SERVICES LLC FAA CRS YHSR-284L                      2732 PERIMETER ROAD, SUITE 101 N. LAS VEGAS NV 89032                      N# N756RW MFG. CESSNA MODEL TR182 S/N R18201142 W.O.                      20-201 DATE 10/23/2020 TACH. 3840.45 SPOH: 1075.35</b> </div>
Date: _____		
A.D. # _____		
Next Inspection Due: _____		
		Signature: _____

Replace broken fairing on propeller bulkhead. As required by F.A.R. 91.409 I certify that this engine Annual inspection was complied with I/AW F.A.R. 43 Appendix D (Scope and Detail of Items To Be Included in Annual and 100-Hour Inspections), and found to be in an airworthy condition. The aircraft and/or component above were repaired and inspected in accordance with Federal Aviation Regulations and are approved for return to service. Pertinent details are on file at this agency under above work order number. **APPROVED FOR RETURN TO SERVICE**

