



PROPELLER MAINTENANCE RECORDS



AERO PUBLICATIONS INC.
ROUTE 79 / P.O. BOX 99 / MORGANVILLE, NJ 07751

PROPELLER MAINTENANCE RECORDS

Log No. _____

Aircraft Registration No. N 3413X

Propeller Manufacturer HARTZELL

Hub Model HC-C2YK-1BF

Blade Design No. F7666A2

Diameter _____

Hub Serial No. CH-11523

Blade Serial No's.

Governor _____

1. C 19754

Model No. _____

2. C 22710

3. _____

Pitch Range

High 29.8° Low 14.0°

Feather _____ Reverse _____

If used on multi-engine aircraft:

Right

Left

Front

Rear

(All applicable information must be filled in)

OWNERSHIP RECORD

Name _____ Date Purchased _____

Address _____

Name _____ Date Purchased _____

Address _____



AERO
TECH PUBLICATIONS INC.

ROUTE 79 / P.O. BOX 99 / MORGANVILLE, NJ 07751

DATE	TOTAL TIME IN SERVICE	TACH RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
7-23-80	2460.27		Propeller overhauled per attached log book. Governor overhauled. J. Callaghan A/P 2166993
11-24-87	2822.7		Prop time since 362.43 Hrs All Entries will be on this log Book Any and all at the log Book are on file with Aft. Secs 1980 Prop Overhaul 934 San Diego Prop A/C ft. Group of K. for R.T.B. 1H2364 Chick [Signature]
12-21-88	3076.1		Prop time since 0.00 615.83 all Entries will be as Certified annual at Annual Inspection Aft. time any Annual Log this date 1A 1552364 Chick [Signature]
12-15-89	3227		<p>Prop. Overhaul & Inspection. AD. 77-12-06 HAWAIIAN PROP. INC. AT 2-90</p> <p>FOOTHILL AIRCRAFT SALES & SERVICE, INC. CABLE AIRPORT, UPLAND, CALIFORNIA 91786 FAA APPROVED REPAIR STATION 4755</p> <p>I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH <u>AD 77-12-06</u> INSP. AND APPROVED FOR RETURN TO SERVICE OTHER DETAILS OF THIS INSPECTION AT THE FACILITY. WO NO <u>5090</u> DATE <u>12-15-89</u> TAC <u>3227</u> T. AC <u>3520</u> ENG <u>263</u> Pkg <u>703</u> NAME <u>[Signature]</u></p>
10-23-90	3378		<p>PROP REMOVED FOR ^{INSPECTION} OVERHAUL THIS DATE, T.A.W. AD 77-12-06. SEE ATTACHED YELLOW TAG. PROP REINSTALLED AFTER INSPECTION. RETURN TO SERVICE. ~END~</p> <p>CALIFORNIA DIVISION OF EL MONTE 2015 SANTA ANITA AVENUE EL MONTE, CA 91731 (909) 678-7100</p> <p><u>Bruce H. White</u> C.R.S. # F.A.A. LGHR-0566 REPAIR STATION</p>

DATE	TOTAL TIME IN SERVICE	TACH RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
3-10-91	411.00		Prop inspected on PTS THIS DATE 1A1882364 Club & Roy Downie
4-8-92	425.21	34290	Prop lube and P.T.S. THIS DATE 1A1882364 Club & Roy Downie
6/8/94	297	3912	ANNUAL INSP FOUND TO BE AIRWORTHY AP3015880720 Lambert, Wally
8295	40393		ANNUAL LUBE AND P.T.S. IN AIRWORTHY COND 1A1882364 Club & Roy Downie
8295	4050.8		6W ANNUAL INSP AND PTS IN AIRWORTHY COND 1A1882364 Club & Roy Downie
9806705 10-5-98	4177.77		6W ANNUAL INSP AND PTS THIS DATE IN AIRWORTHY COND AP 1A1882364 Club & Roy Downie

PROP MODEL HC-C2YK-1BF
PROP SN CH115223
REG NO N3413X
WORK ORDER 464-07-2001

Ron's Aircraft Service, Inc.

2810 Perimeter, Suite 101
North Las Vegas, NV 89032
Repair Station No. RJUR641K

DATE 10/17/01
TTP 4906.9
TSPON 1,755.60
TACH 4,215.90

Prop Entries

This Propeller has been inspected as part of an Annual/100 hour inspection and was found to be in airworthy condition...

DATE 10/17/01

SIGNED: *Ronald K Beard*

WORK ORDER 464-07-2001

Certified Repair Station No. RJUR641K

PROP MODEL HC-C2YK-1BF
PROP SN CH115223
REG NO N3413X
WORK ORDER 1055-01-2003

Ron's Aircraft Service, Inc.

2810 Perimeter, Suite 101
North Las Vegas, NV 89032

Repair Station No. RJUR641K

DATE 2/12/03
ATA 4,915.19
TTP 4,915.19
TSPON 1,763.89
TACH 4,224.19

Prop Entries

Flushed old grease out of prop and lubed prop with Aeroshell #8... This Propeller has been inspected as part of an Annual/100 hour inspection and was found to be in airworthy condition...

DATE 2/12/03

SIGNED: *Ronald K Beard*

WORK ORDER 1055-01-2003

Certified Repair Station No. RJUR641K

PROP MODEL HC-C2YK-1BF
PROP SN CH115223
REG NO N3413X
WORK ORDER 1741-04-2004

Ron's Aircraft Service, Inc.

Repair Station No. RJUR641K
2810 Perimeter Road, Suite 101
North Las Vegas, NV 89032
Phone: 702-646-6191

DATE 5/20/2004
AC TSN 4921.11
PROP TT 4921.11
TSPON 1768.81
TACH 4230.11

Prop Entries

This Propeller has been inspected as part of an Annual/100 hour inspection and was found to be in airworthy condition...

DATE 5/20/2004

SIGNED: *Ronald K Beard*

Work Order 1741-04-2004

Printed by EBIS 3 (datcomedia.com)

DATE	TOTAL TIME IN SERVICE	TACH RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
11-15-04	000.0	426.9	TACH REPLACED THIS DATE OLD TACH TIME 426.4
	SMOH	1786.6	NEW TACH TIME IS 000.0 <i>Change to</i>
			AD 2003-13-17 <i>APUG 422804</i> N/A <i>1/1</i> <i>5/8/04 9245</i>
			<p>I CERTIFY THAT THIS <i>Prop</i> HAS BEEN INSPECTED IN ACCORDANCE WITH A <i>720</i> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AND IS HEREBY APPROVED FOR RETURN TO SERVICE.</p> <p>TACH TIME <i>28.2</i> DATE <i>3 July 05</i></p> <p>HOBBS _____ TTE _____</p> <p>TAF _____ TSMOH <i>1914.8</i></p> <p>A & B P/N/O <i>53944 9245</i></p> <p>SIGNATURE <i>[Signature]</i></p>
			" "
8/15/05		1926.7	" " <i>Prop</i>
8/15/05	SMOH	1926.7	<i>Prop</i> completely overhauled T.A.W. HANTZELL SERVICE MANUAL #113B, 133C, 202A ALL A/D'S AND HANTZELL SB'S AND SL'S Complied with to DATE pertinent details of this overhaul are on file under WO 05-226 at the following repair facility NEVADA PROPELLER & ACCESSORIES INC. 2732 PERIMETER RD., N. LAS VEGAS NV 89032 FAA CRS # U6XR0874
8/15/05		" "	" " Installed propeller on aircraft <i>Prop</i> and safety ASP # SB0-75-2647
7/7/06		45.5	" " 100 Hr SERVICE Following HANTZELL SERVICE MANUAL
	45.5		DRESS LEAD EDGE FOR NICKS TPT 192479 TSMOH <i>13.8</i> 4264.9 <i>From Raming A/P 545644260</i>

DATE	TOTAL TIME IN SERVICE	TACH RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
8/5/07	60.3	60.3	THIS PROPELLER HAS BEEN INSPECTED AS PART OF AN ANNUAL INSPECTION AND FOUND TO BE IN ^{EX} AIR WORTHY CONDITION AD 06-18-15 N/A PER IENIGWA MODEL AND RETURNED TO SERVICE. <i>Tom Baring AIP IA 545644760</i>
6 Sept 2008		72.4	Annual inspection complied with per 14 CFR Part 43 Appendix D and check list. <i>Ray Johnson 2773344 IA</i>

PROP MODEL
PROP SN
REG NO N9825G
WORK ORDER
0163-10-2009



Elite Aircraft Services, LLC.

2634 Airport Drive
North Las Vegas, NV 89032
Phone (702) 835-1220

DATE 10/27/2009
A/C TSN: 4352.1
PROP TT: 4352.1
TSPOH: 75.5
TACH: 105.2

Prop Entries

I certify that this propeller has been inspected in accordance with a 100 Hr. inspection and was determined to be in airworthy condition. Dressed and painted prop.

The aircraft and/or component(s) on was repaired and inspected in accordance with current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under this work order number.

DATE: 10/27/2009

SIGNED

Philip John Swibes, IA 2584811

Work Order: 0163-10-2009

Printed by EBis 3 (datcomedia.com)

2 Feb 25 2009	114.9		Annual inspection complied with per 14 CFR Part 43 Appendix D and Checklist. <i>Ray Johnson 2773344 IA</i>
---------------	-------	--	---



AMERITECH INDUSTRIES DBA
AMERICAN PROPELLER SERVICE
REPAIR STATION NO. N03R717L
20208 CHARLANNE DRIVE
REDDING, CA 96002 USA

WORK ACCOMPLISHED

Complied With A.D. 2009-22-03

MODEL NO. *HC-C2VK-1BF*

SERIAL NO. *CH3952E*

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER

REPAIR ORDER # *25907-05-2021*

DATED: *06-02-2021*

SIGNED

Mike Crowell
(AUTHORIZED INDIVIDUAL)

MIKE CROWELL

FORM LB01

