

BEECH F33A N6393S
S/N: CE-623
PROPELLER LOG # 1



SANTA MONICA PROPELLER

Propeller Logbook

3025 AIRPORT AVENUE, SANTA MONICA, CALIF. 90405-6186
PHONE #: 1-800-421-9995

SANTA MONICA PROPELLER INC

3025 AIRPORT AVENUE
SANTA MONICA
CALIFORNIA 90405-6186



FAA REPAIR STATION 4015
TELEX 182028 M PROP SNM
(213) 390-6233

SERVICEABLE PARTS TAG

CUSTOMER General Aviation W.O. NO. 18768-1044 DATE 4-12-89
MODEL NO. 3A32C76M/S20NB2 DESCRIPTION McCauley prop
SERIAL NO. 756649/K59688, K59990, FL00645 QUANTITY
Completely Overhauled Angles Corrected Steel Parts Magnafuxed & Cadmium Plated
AD's, SB's, SL's Incorporated New Blades Installed Aluminum Hub Penetrant Insp., Anodized
Part Repaired Only New Electric Deice Installed . Blades Penetrant Insp., Anodized
New Seals Installed Only New Alcohol Deice Installed . Blades Penetrant Insp., Alodined.....
Blade Damage Repaired..... Parts Inspected Only Blade Shanks Compression Rolled.....
Hub Exchanged w/OHC Unit AD, SB Compliance Only..... Blades Edge Trimmed & Painted.....
Hub Exchanged w/New Unit Governor RPM Tested & Set Propeller Assembled, Lubricated, Balanced.

REMARKS

1 blade rejected due to impact damage.

SEE REVERSE FOR AUTHORIZATION

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model 3A32C76SM

Blade Design S82NB-2

Diameter 80"

Hub Ser No 756649

Blade Ser Nos _____

No 1 K59688 YS

No 2 K59990 YS

No 3 FL006 YS

No 4 _____

No 5 _____

PITCH RANGE

High 29.0° Low 13.3°

Feather Reverse

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____


PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

DESCRIPTION OF ALL OPERATIONS
 PERTAINING TO AIRWORTHINESS DIRECTIVES,
 SERVICE BULLETINS, SERVICE LETTERS,
 & MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
13 APRIL 89		Propeller completely overhauled replaced # 3 BLADE. ALL A.D. & MICHAULT S.B. S.L. Complied with TO DATE.	
		THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY. REFER THIS INVOICE NUMBER AND DATE.	
		SIGNED  CERT. #2317700 AUTHORIZED SIGNATURE F.A.A. A.R.S. NO. 4015	

WARRANTY

(READ AND INSERT IN AIRCRAFT LOG BOOK)

AIRCRAFT OWNER PLEASE NOTE:

Santa Monica Propeller Inc., thanks you for purchasing this propeller or overhaul from our facility.

Santa Monica Propeller Inc., is proud to offer what we believe to be the most comprehensive **WARRANTY** in the aviation industry.

Santa Monica Propeller Inc., warrants this propeller to be free of defects in material and craftsmanship for TWO (2) YEARS or ONE THOUSAND (1,000) HOURS from time of overhaul, whichever comes first.

This **WARRANTY** is not pro-rated and includes commercial usage. This **WARRANTY** entitles purchaser to repairs by **Santa Monica Propeller Inc.**, only.

Assemblies must be shipped prepaid and will be returned within five (5) working days F.O.B. **Santa Monica Propeller Inc.**.

Assemblies must be accompanied by the original work order (invoice).
NO EXCEPTIONS.

This **WARRANTY** is transferable per conditions on reverse.



**SANTA MONICA
PROPELLER**

FAA ARS 4015
(213) 390-6233

TOLL FREE

(800) 421-9995

3025 Airport Ave. Santa Monica CA 90405

W. L. ...
Authorized Signature

18768
Work Order #

4/12/89
Date

DATE

4/13/89


141.3 SMOH 4-13-89

162.09 SMOH
ON 4-13-89

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		Verify that the propeller has been inspected in accordance with an <u>Annual</u> inspection and was determined to be in an airworthy condition	
Propeller T. T.	141.3	SMOH ON 4-13-89	
Model No.	McCauley	3A32C76	Verify that this propeller has been inspected in accordance with an <u>Annual</u> inspection and was determined to be in an airworthy condition
Serial No.	756449	4053	Propeller T. T. 162.09 SMOH ON 4-13-89
Date of Inspection	1-4-94		Model No. McCauley 3A32C76
			Serial No. 756449
2161 E Avion St., Ontario, CA 91761			Date of Inspection 2-1-95 Work Order 4562
<i>D. J. H. B.</i>			UNITED BEECHCRAFT
			2161 E Avion St., Ontario, CA 91761
			Repair Station, CNZR 924C
			<i>D. J. H. B.</i> Inspector


DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		AIRCOMBAT MAINTENANCE 230 N. DALE PL. FULLERTON, CALIF. 92833 (714) 522-4710	
		REG #: N6393S TACH: 1667.7 Date: 08-05-1999 SPMH: 1667.7	PROP T: 1667.7
		I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HR INSPECTION AND WAS DETERMINED TO BE AIRWORTHY AT THIS TIME AND DATE ONLY.	
			
		LARRY VIDAL 550795411	

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES.
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
SEPTEMBER 20 2000	1661.95 hr	TBOH: 202.61 hr REMOVED SPINNERS, VISUAL INSPECTION OF PROPELLER HUB, SPINNERS AND BULKHEAD, DRESSED AND PAVED BLADES c/w 40-100 hr and annual items per BSOA Service Manual. I CERTIFY THAT I HAVE INSPECTED THIS PROPELLER IN ACCORDANCE WITH A 100 hr INSPECTION AND DETERMINED IT TO BE IN AN AIRWORTHY CONDITION THIS DATE. Ted W. Clark A: P332957	
SEPTEMBER 20 2000	1661.95 hr	TBOH: 202.61 hr CITATED APPLICABLE AD NO. 20-18. I CERTIFY THAT I HAVE INSPECTED THIS PROPELLER IN ACCORDANCE WITH AN ANNUAL INSPECTION AND DETERMINED IT TO BE IN AN AIRWORTHY CONDITION THIS DATE.	Ted W. Clark A: P332957 IA.
NOTE: UPDATED AD	LIST	IN BACK OF LOG	

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number Service Instruction/Service Advisory	Authorized Signatures Repairman and Station Certificate Numbers
13 April 89		00:00	SB 99, SB 99-1, SB 99-2,	SB 106, SB 118,
			SB 140, SB 140-1, SB 150, SL 74-3,	
			SL 81-10, SL 83-8-1, SL 87-3.	
				
				CERT. #2317790

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number Service Instruction/Service Advisory	Authorized Signatures Repairman and Station Certificate Numbers
10/12/02 Tach		1792	Annual inspection completed Per FAR 43 appendix D Hugh J. Gallagher	completed 17438745876
10/13/03 Tach		1837	Annual inspection completed Per FAR 43 appendix D Hugh J. Gallagher	completed 17438745876

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number Service Instruction/Service Advisory	Authorized Signatures Repairman and Station Certificate Numbers
4/6/04	Tach	1837	Annual inspection completed Per FAR 73 approved	Hugh J. Galley 174387458 IA
10/2/05	TACH	1970	I certify This propeller has been inspected IAW A 100 hr inspection AND Found to be in Airworthy condition on this date and time only	Michael Lee AEP 2733887