AIRCRAFT TECHNICAL RECORD

Section 3. ENGINE LOG

1. Approving Competent Authority /Country Austro Control GmbH Austria			AUTHORISED RELEA	3. Form Tracking	3. Form Tracking Number AE021616				
4. Organisa	tion Name and Address:		Austro Engli Rudolf Diesel 2700 Wiener Neus	Straße 11			5. Work Order /	Contract / Invoice ES180589	
6. Item	7. Description		8. Part No.	8. Part No. 9. Oty.		10. Serial No.		11. Status/Work	
1	1 E4PC Engine E4PC-00			E4PC-00-000-000 lss.: 004		E4P-C-00	203	New	
3a. Certifie		above were manufactured in comformity to: and are in condition for safe operation		Certifies that unles		to Service Code of the work of the service of the s		ock 12	
. 91				THE RESIDENCE OF THE PROPERTY	the items are con	sidered ready for relese	to service.		
\	non-approved design of	ata specified in block 12		respect to that wor	Too homs are con	isidered ready for release			
3b. Authori	non-approved design of sed Signature	13c. Approval / Autor	risation Number 1G.0010	14b. Authorised S		Socied ready for readse	14c. Certificate/ Approval Re	f. Number	
13b. Authori		13c. Approval / Autor		06		Socied ready for readse		f. Number	

EASA Form 1 - 21 Issue 2

Freigabe: 24.Aug. 2010 / M. Nemec

FOQ05_Form1_rev1

ENGINE DATA

1.	маке	HUSTRO Engine GmbH
2.	Model	EUP-C
3.	Specification	E00081EN
4.	Manufacturer's Serial Number	E4P-C-00203
5.	Date of Manufacture	September 2018
		-PH

Section 3A: Engine Service and Maintenance Log

	1994				
DATE	TIME RUN	TIME SINCE OVERHAUL	CY	CLES	DESCRIPTION OF WORK BEREORMED:
1 1	HOURS min	HOURS min	S u b Total	TOTAL	DESCRIPTION OF WORK PERFORMED: (INSPECTION, REPAIRS, REPLACEMENT)
BROUGHT					
Registration Antraine Total Time Engine RH SN Engine E4P, S S/N: 62.083, F Total Time En EECU softwar Engine and do STC's incorpo All applicable complied with AWD Bi-week Refer to Australispection/exc	RCRAFT N1615W AC Ser Work Co E4P-C-00203 RIGHT Igine brought forward re installed: VC33_2 commentation inspect orated, none found. Riy checked thru 20 To MM E4.08.04, late change intervals on due: 100 hr inspect on due: 100 hr inspect	nstalled on Aircraft Date 30.6 hrs P_06_21 ted for Major Mod's a rectives, Service Bullets revision for composition	A 62 and/or lletins ment		
	I I	Ţ	[]		
Diamond RH Engin	W (RH Engil DA-62 S/N: 62.08 ne M/N: E4P-C ed the following n	83 S	N: E4P-0	C-00203	Eng TT: 109.0
1. Per 2. Th 3. Dr ner 4. Re 1 certify the be in airw approved Daytona	rformed a 100 Ho is was the Engine ained the engine w oil filter and ser moved, cleaned, s nat this Engine ha	our inspection refer oil. Removed, cut rviced the engine viserviced, and reinst as been inspected in Work performed ce. Details are on f	open, and vith 6.5 qualitation accordant in	inspected the larts of Aerosi Gearbox Screece with a 100 ance with the	A-62 Maintenance Manual. all manufacturer required items. e oil filter, no defects noted. Installed a hell Ultra Diesel 5W30 oil. en, serviced the gearbox as required. O Hour inspection and was determined to current regulations of the FAA and is n under W0 #1486) ature:
	Beach, Florida 3	2114	END		FAA CRS DYTR262K
	 				
THIS PAGE TOTALS					
PREVIOUS TOTALS					
TOTALS SINCE NEW					CARRY FORWARD to Top of Next Page

					NAME/ SIGNATURE	LICENCE: AMEOR AMO/ACA
	1/15W (DIL Engine)	DA	TONA	•		
	1615W (RH Engine) amond DA-62 S/N: 62 083	AIRCRAF	T SERVICES	4	11/13/2019 Tach: 137.7	
	H Engine M/N: E4P-C		S/N: E4P-C-00203		Eng TT: 137.7	
Pe	erformed the following main		anaina tha Diamand DA 63			
			encing the Diamond DA-62 open, and inspected the oil			
	new oil filter and service	ed the engine v	with 6.5 quarts of Aeroshell	Ultra Diesel	5W30 oil.	
			stalled the Gearbox Screen, s stalled the Induction Air Filte		•	
	certify that this Engine has be	en inspected i	in accordance with an Annua	al inspectio	n and was determined to	
	proved for return to service. I			, -		-
	aytona Aircraft Services, Inc		me at this Repair Station und		00//	
	1 Pearl Harbor Drive		Authorized Signatur	e: <u> </u>	Memos	
	aytona Beach, Florida 32114		FND		FAA CRS DYTR262K	
			-		I	
	ENGINE MODEL: E4P-C	<u></u>	Promier Alcorett Senden Inc		DATE: 12/7/2000	
		remier	Premier Aircraft Service,. Inc. 5540 NW 23rd Avenue Hanger 14		DATE: 12/7/2020 A/C TSN: 212.8 ENG TT (R): 212.8	
	WORK ORDER: 9150-11-2020		Fort Lauderdale, FL 33309 Phone: (954) 334-2393		TACH: 212.8	10.4-1975
	Right Engine Entries					
	CON ENLUGIUM AS A GUIDE	:. SERVICED ENG	NE IAW 14 CFR PART 43 APPENDIX INE WITH 7 LITERS OF AEROSHEL	I DIEGEL LILTE	DA EWIN AND NEW	
	RUN AND LEAK CHECKED	OK ADS CHECK	EPLACED FUEL FILTER WITH NEW ED THROUGH CURRENT ON ATP N	P/N WK724_3	ENGINE WAS GROUND	
	INSTALLED IAW PARIH) D	REVENT FAILURE URING MFG. TER	OF TURBO WASTE GATE CONTRO	L ROD —PCW		
	121/142 2000 101 240 (JIL DROWN VALVE	VERSION VC33-2P-06-24 (20-02-202 WITH NEW P/N D44-9071-06-01 I.IA	W ALICTOA E	4 00 04 14 14 011	
	M.M. CH 79-00-00.	AND REINSTALL	ED OIL BREATHER VALVE ON RIGH	TENGINE I.A.	W. AUSTRO E4.08.04	
	DETERMINED TO BE IN A	E, ENGINE, OR PI	ROPELLER HAS BEEN INSPECTED	IAW AN ANNU	AL INSPECTION AND WAS	
	DATE: 12/7/2020	SIGNED:	20 Month Munico		Work Order: 9150-11-2020	
		EMMANUEL	VICIOSO		by EBis 3 (datcomedia.com)	
		CRS 9PAK40	J28		, , , , , , , , , , , , , , , , , , , ,	
						19 7-22
	ENGINE MODEL: E4P-C	∞ `	Premier Aircraft Service,. Inc.		DATE: 8/4/2021	
	ENGINE SAN (R):	Premier	5540 NW 23rd Avenue Hanger 14 Fort Lauderdale, FL 33309		A/C TSN: 312.3 ENG TT (R): 312.3	
	REG. NO: 1615W WORK ORDER: 9449-07-2021	ircraft Service	Phone: (954) 334-2393		TACH: 312.3	
	Right Engine Entries					
	KIT PN: E4A-00-301-KIT. S	SERVICED WITH 7	NE IAW AUSTRO E4.08.04 MM CH 5- 7 LITERS OF AEROSHELL DIESEL 5	W30 REPLAC	ED FUEL FILTER WITH	
	75W-80. ENGINE RUN UF	CHECKED GOO				
	DÉFECTS NOTED AT THI	S TIME.	ISPECTION ON RH ENGINE IAW: AL			
	AT THIS TIME.		INSPECTION IAW: AUSTRO E4.08.0			
	BELT PN E4A-74-000-801		REPLACEMENT IAW: AUSTRO E4.0		5-40-00. INSTALLED NEW	
		"[2017] [2017] [2017] [2017] [2017] [2017] [2017]	MODIFICATION OF PRESSURE VAL CO-RING AS REQUIRED.	VE HUSE		
			PROPELLER HAS BEEN INSPECTED TO BE IN AIRWORTHY CONDITION		PART 43 APPENDIX-D 100	
	DATE: 8/4/2021	SIGNED:	20/ Month much	MO	Work Order: 9449-07-2021	
		EMMANUE	Vicioso		d by EBis 3 (detcomedia.com)	
		CRS 9PRA	7020			

Section 3A: Engine Service and Maintenance Log

-	ENGINE MODEL E4P-C ENGINE SN (R): E4P-C-00203 REG NO 1815W WORK ORDER: 9500-08-2021 Right Engine Entr	Premier 5540 M For La	or Aircraft Service,. Inc. N 23rd Avenue Hanger 14 Identale, FL 33309 (954) 334-2393	DATE: 9/17/2021 A/C TSN: 328.1 ENG TT (R): 328.1 TACH: 328.1	F WORK PERFORMED:
-	THE DEDLACED BH	ING UPPER COOLANT LINE	WITH NEW P/N E4A-06-000 R RH ENG. N/A BY S/N) HP FUEL PUMP GEAR- R	-801 IAW DA62 MM CH 75-00. H ENG. N/A BY CYLINDER HEAD ASSY	
	DATE: 9/17/2021	SIGNED:	Admilletune	Work Order: 9500-09-2021	
-		CRS 9PR9402B	SO	Printed by EBis 3 (detcomedia.com)	
•	1				
	INGINE MODEL E4P-C	<i>/ ·</i> ·	l Vircraft Service,. Inc.	DATE: 1/17/2022 A/C TSN: 362.7	
E	4P-C-00203	Aircraft Service Phone: (954	rd Avenue Hanger 14 Sele, FL 33309) 334-2393	ENG TT (R): 362.7 TACH: 362.7	1
—— (4 ——— (5	64.08.04 MM INSPECTION PLTRA 5W30 AND NEW ENGINE WAS GROUND 18) C/W MSB-E4-036 H 36) REPLACED RH ENG	CTION ON RH ENGINE IAW 1- ON CHECKLIST AS A GUIDE. S ENGINE OIL FILTER PIN E4A- RUN AND LEAK CHECKED O PP INSPECTION AND REPLA SINE OIL SERVICE CAP WITH	SERVICED ENGINE WITH 6 52-100-802 REPLACED FL K. ADs CHECKED THROUG CEMENT. N/A BY HPP S/N. NEW PN DIN3771-37 77X2	D, USING DA62 MM CH 5 AND AUSTRO LITERS OF AEROSHELL DIESEL IEL FILTER WITH NEW P/N WK724_3 H CURRENT ON ATP NAVIGATOR. 62 AS REQUIRED.	
(3	CERTIFY THIS AIRFRA	GINE VALVE COVER IAW WIT	TH DA62 CH 51.	W AN ANNUAL INSPECTION AND WAS	
<u>_</u>	ATE 1/17/2022		mull/munces	Work Order: 9635-12-2021	<u> </u>
		CRS 9PRR402B		Printed by EBis 3 (datcomedia com)	
	ENGINE MODEL E4P-C ENGINE S/N (R)	(11) .	er Aircraft Service,. Inc.	DATE: 4/26/2022 A/C TSN: 386.9	
	REG. NO: 1615W WORK ORDER: 9615-04-2022 Right Engine Entri	Aircraft Service Phone:	V 23rd Avenue Hanger 14 derdale, FL 33309 954) 334-2393	ENG TT (R): 386.9 TACH: 386.9	
		E4-08-04 MM CH 81. ENG RU	N UP CHECKED GOOD	SATE CONTROLLER WITH NEW P/N	
	DATE: 4/26/2022	SIGNED: SIGNED: VICIOS CRS 9PRR402B	orman human	Work Order: 9815-04-2022 Printed by EBis 3 (datcomedia.com)	
	1 1	1 1	ı	f	
IS PAGE					
EVIOUS					
TALS CE NEW				CARRY FORWARD to Top of Next Pa	nge L

					LICENCE: AMEOR AMO/ACA
	ENGINE MODEL: E4P- ENGINE S/N (R): E4P-C-00203 REG. NO: 1615W WORK ORDER: 9977-09-2022	Premier Aircraft 5540 NW 23rd Aven Fort Lauderdale, FL Phone: (954) 334-23	ue Henger 14 33309	DATE: 9/9/2022 A/C TBN: 455.2 ENG TT (R): 455.2 TACH: 455.2	
	(4) CAV (DA62) 10 CHECKLIST, SERV PAN E4A-52-100-80 CHECKED OK, AD (10) REMOVED AD (11) REMOVED AD	OHR INSPECTION ON RH ENGINE IAW DO VICED ENGINE WITH 7 LITERS OF AERO VICED ENGINE WITH 7 LITERS OF AERO VICED ENGINE FILTER WITH NEW VID REPLACED THROUGH CURRENT ON AT VID REPLACED O-RING'S ON LH AND RH VID REPLACED O-RING ON RH ENGINE OF VID REPLACE RH ENGINE FADEC WITH SO VIM CHAPTER 78. PERFORMED ENGINE OF	PIN WK724_3 ENGINE WAS C IP NAVIGATOR. ENGINE'S DIP STICKS IAW AI IL LEVEL AND TEMP SENSOI	USTRO MM CHAPTER 79 R IAW AUSTRO MM CHAPTER	
		SIGNED	S	Work Order: 9977-09-2022	0
	DATE: 9/9/2022	SAMUEL TAVAREZ JR. CRS 9PRR402B	P	rinted by EBis 3 (datcomedia.com)	
					1
	ENGINE MODEL: E4P-C ENGINE SAN (R):	Premier Aircraft Servi	ce,. Inc.	DATE: 11/4/2022 A/C TSN: 464	
	E4P-C-00203	reraft Service S540 NW 23rd Avenue Hang Fort Lauderdale, FL 33300 Phone: (954) 334-2393	or 14	ENG TT (R): 464 TACH: 464	
	Right Engine Entries				
	E4.08.04 MM INSPECTION ULTRA 5W30 AND NEW E ENGINE WAS GROUND R (27) MSB-E4-039 OIL ANA (28) REPLACED RH ENGINE 73.PERFORMED ENGINE (30) REPLACED RH ENG	TION ON RIGHT ENGINE IAW 14 CFR PAI I CHECKLIST AS A GUIDE. SERVICED EN NGINE OIL FILTER P/N E4A-52-100-802. UN AND LEAK CHECKED OK. ADS CHEC LYSIS AND PISTON REPLACEMENT — N/A HP FUEL PUMP BASE GASKET WITH NEW RUN. OPS CHECKED GOOD. NO LEAKS INTAKE MANIFOLD TO GEARBOX COOL	IGINE WITH 7 LITERS OF AE REPLACED FUEL FILTER WI' KED THROUGH CURRENT O A BY S/N. W P/N DIN3771_44X3_ACM70 DETECTED AT THIS TIME.	ROSHELL DIESEL TH NEW P/N WK724_3 N ATP NAVIGATOR. DIAW E4-08-04 MM CH	
		E, ENGINE, OR PROPELLER HAS BEEN	INSPECTED IAW AN ANNUA	L INSPECTION AND WAS	
	DETERMINED TO BE IN A DATE: 11/4/2022	SIGNED: 2000/100	muce "	ork Order: 10019-10-2022	
		EMMANUEL VICIOSO CRS 9PRR402B	Printed by	EBis 3 (datcomedia.com)	
				1	
	N1516W	Engine Log	BK	May 12, 2	023
TTIS: 57		E4P-C R/H E4P-C-0		TTSO: 57	3.2
inspected Ge	earbox element and sen	engine I.A.W. DA 62 Diamond A 00-802 Aeroshell Diesel Ultra 7Q viced gearbox oil N1. Serviced Ri heck engine, no leaks noted. Rec	TS. Removed & replace TS. Removed & replace	ne M/M. Removed and repla d fuel filter, PN# WK724_3. R	ced Oil
		is compliance with 100 HR insp			rned to
James Catchi	ngs I/A & A/P 2769658	Jeremiah Gray A/P #4792396	2 Cato	hy)	
				-	

Section 3A: Engine Service and Maintenance Log

A MICHE	v	Dight Engine Land		RMED
N1615V	v Model-E4PC	Right Engine Log I SN: E4P-C-0020	200 (200 (200 (200 (200 (200 (200 (200	July 12, 2023
mplied with 600-ho sembly, PN: E4PB- : 07279. Complied A-30-000-000, SN: 09-05-02-01335. C	ur replacement of Two-Novement	Mass Flywheel and Hub A Installed NEW Two-Mass ent of High Pressure Fuel stalled NEW High Pressure eplacement of Wastegate on on R. Engine. Replace	Assembly. Removed Two-Mass Flywhers Flywheel and Hub Assembly, PN: E4 Pump. Removed High Pressure Fuel re Fuel Pump, PN: E4A-30-000-BHY, See Controller Circlip and 600-hour flushed gearbox filter and replenished gearbox	PB-73-000-000, Pump, PN: SN: and replenishment ox oil with Shell
irax 75W-80. Install roshell Diesel Ultra.	Removed exhaust show erational and leak-check	ed fuel system. Changed ck meant and installed ne	engine oil and filter and replenished washock mount. Work performed IAW leaks noted. Rechecked all fluid quan	ith 7 quarts ———— DA 62 MM and
	11	- - - - - -	1	
			•	
				·
PAGE	+			
/IOUS	+			
ALS				
TALS E NEW			CARRY FORWARD to Top of Next	200

CARRY FORWARD to Top of Next Page