


N 15666

Front  Rear   
Left  Right



**AMERITECH INDUSTRIES, INC**  
Where Performance Begins...®

# PROPELLER LOGBOOK

**Ameritech Industries, Inc.**  
dba: American Propeller Service

**FAA REPAIR STATION #NO3R717L**

**[www.ameritech-aviation.com](http://www.ameritech-aviation.com)**  
**[sales@ameritech-aviation.com](mailto:sales@ameritech-aviation.com)**

**20208 Charlanne Drive**  
**Redding, California 96002, U.S.A.**  
**(530) 221-4470 / (800) 292-7767**

# PROPELLER MAINTENANCE RECORDS

Log No. \_\_\_\_\_

Aircraft Registration No. \_\_\_\_\_

Propeller Manufacturer Hartzell

Hub Model HC-C2YK-1BF

Hub Serial No. NS3223B

Blade Design No. F8468A-4

Blade Serial No's.

1. E84373

2. E84249

3. \_\_\_\_\_

4. \_\_\_\_\_

5. \_\_\_\_\_

6. \_\_\_\_\_

Pitch Range:

Low 13.5 High 27.0

Feather \_\_\_\_\_ Reverse \_\_\_\_\_



Governor Manufacturer Hartzell

Model No. F-4-3A

Serial No. 7129U

For current TBO's call: 1.800.292.7767



DATE	TSN	TSO	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
02/20/17		0-0	 <p>AMERITECH INDUSTRIES DBA AMERICAN PROPELLER SERVICE REPAIR STATION No. NO3R717L 20208 CHARLANNE DRIVE REDDING, CA 96002 USA</p> <p>WORK ACCOMPLISHED <u>Overhauled</u></p> <p>MODEL NO. <u>HC-C2YK-1BF</u></p> <p>SERIAL NO. <u>NS3223B</u></p> <p>THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER</p> <p>REPAIR ORDER # <u>21380-02-2017</u></p> <p>DATED: <u>02-20-2017</u></p> <p>SIGNED  <b>MIKE CROWELL</b> (AUTHORIZED INDIVIDUAL)</p>


FORM LB01

**EGA Aviation, Inc.**  
2642 Airport Dr.  
North Las Vegas, Nv. 89032 (702) 683-7507  
Prop Logbook  
WO # N/A

N15666  
Tach: 5097.5  
C/W ANNUAL insp. IAW PIPER PA-28-235 MM and checklist. Install prior removed propeller overhauled by AMERICAN PROPELLER SERVICE under WO# 21380-02-2017. Installed with new "O" ring and torqued IAW MM. and secured with lockwire. Reinstalled and secured spinner. All AD,s checked and C/Wed to date. Post maint. run up indicates all op,s normal and no leaks noted at this time.

1 Aug. 2017  
TTSO:0000.0

I certify this propeller has been inspected IAW a ANNUAL insp. and has been determined to be in an airworthy condition.

  
Lennie John Guerin 21483690 A/P IA

**EGA Aviation, Inc.**  
2642 Airport Dr.  
N. Las Vegas, NV. 89032  
(702) 683-7507

N15666  
Tach:5153.11 HC-C2YK-1BF  
C/W ANNUAL insp. IAW Cessna C-152 checklist and MM. Removed spinner and inspected prop mounting bolts. Serviced prop hub HARTZELL service manual dressed and painted prop. Reinstalled and secured spinner. All AD,s checked and C/Wed to date.

1 Aug. 2018

Propeller Logbook  
WO# N/A S/N NS3223B TTSO:0055.61

Post maint. run up indicates all op,s normal and no leaks noted at this time. I certify this PROPELLER has been insp. IAW a ANNUAL insp. and has been determined to be in an airworthy condition.

Lennie John Guerin 21483690 A/P IA

