LOGGOOK OPENED 19 TUNE 2017 @ TACH: 0811.4 N 8\$R. Front & Rear □ Left □ Right □



AMERITECH INDUSTRIES, INC ®...® Where Performance Begins

## PROPELLER LOGBOOK

Ameritech Industries, Inc. dba: American Propeller Service

FAA REPAIR STATION #NO3R717L

www.ameritech-aviation.com sales@ameritech-aviation.com

20208 Charlanne Drive Redding, California 96002, U.S.A. (530) 221-4470 / (800) 292-7767

## PROPELLER MAINTENANCE RECORDS

Log No				
Aircraft Registration No.				
Propeller Manufacturer MT-Propeller				
Hub Serial No/200/2_				
Blade Design No. /88-30d				
Blade Serial No's.				
1. <u>ACK-44500</u>				
2. ACK-44501				
3. ACK-44502				
4				
5				
6				
Pitch Range:				
Low				
Feather	Reverse			
Model No				
Serial No.				

For current TBO's call: 1.800.292.7767

MT Rop + WIE gHT 45. 6 1B5 INSTALLED PROPELLER + SpINNER WEIGHT.

Page No.

			rage No
DATE	TSN	TSO	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
06/12/2017		0.0	AMERITECH INDUSTRIES DIA  AMERICAN PROPELLER SERVICE REPAIR STATION No. NO3R717L 2020E CHARLANNE DRIVE REDDING, CA 96002 USA
			WORKACCOMPLISHED Overhouled
			MODEL NO. MTV-12-D
			SERIAL NO. 120012
			THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEBERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER
			REPAIR ORDER# 21706-05-2017
			DATED: 06-12-2017
			SIGNED MIKE CROWELL  (AUTHORIZED INDIVIDUAL)
			FORM LB01
	AMERICA	ed prior removed AN PROPELLER SI	EGA Aviation Inc. 2642 Airport Drive N. Las Vegas, NV. 89032 (702) 683-7507 Propeller Logbook 19 Jun 2017 WO# 2658 Total Ti OOOOO
	Post maii	nt. run up and cy eturned to servic	rcle of prop indicates all op,s normal and no leaks noted .
		3	This propeller has been Dynamically Balanced using a Chadwick Helmuth Vibrex Balance System. IPS before IPS after Complete Grams Authorized Signature Mark Local IA2159073  Complete Ten Co
			. /
-	-		
	**	1./	
		"	

DATE	TSN	TSO	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK			
			AMERITECH INDUSTRIES DBA AMERICAN PROPELLER SERVICE REPAIR STATION NO. NO3R717L 2020B CHARLANNE ORIVE 0 REDDING, CA 96002 USA			
		ACCOMPLISHED	Repaired Mounting Stud			
	MODE		V-I2-D			
	THE AI AND IN	RCRAFT AND/OR CO ISPECTED IN ACCOR ATIONS AND IS APP HENT DETAILS OF TH	OMPONENT IDENTIFIED ABOVE WAS REPAIRED IDANCE WITH CURRENT FEDERAL AVIATION ROVED FOR RETURN TO SERVICE. IE REPAIR ARE ON FILE AT THIS AGENCY UNDER			
		_	2095-10-2017			
	DATED	10.05	- <u>2017</u>			
	SIGNE	- m	/- (AUTHORIZED INDIVIDUAL)			
			FORM LB01			
			EGA Aviation, Inc. 2642 Airport Dr. N. Las Yegas, NV. 89032 (702) 683-7507 N8SR (702) 683-7507 N8SR Propeiler Logbook Tach:0841.8 W0 2887 Installed prior removed propeiler Model # MTV-12-D S/N 120012 for repair of mounting stud by AMERICAN PROPELLER SERVICE under W0# 22095-10-2017. Installed propeiler with new "0" ring and torqued IAW MM and secured. Install spinner. Post maint. run up indicates all op,s normal and no leaks noted at this time.			
			Aircraft returned to service Lennie John Guerin 21483690 A/P IA			
	,,,		do-fle Dre-			
		,	EGA Aviation, Inc.			
		_	2642 Airport Dr. N. Las Vegas, NV. 89032			
		N8SR Tach:09	(702) 683-7507  Propeller logbook 8 May 2018 951.1 WO#3211 TTS0:0139.7			
		C/W AN	NUAL inspection IAW Piper PA-28R-201T checklist and MM. Removed . Inspected prop mounting hardware and prop hub with no defects			
		26-13 f — All AD,s	Dressed and painted prop. Reinstalled and secured spinner.AD 2007- ound N/A by date and MT type prop installed on Jan. 2012. s checked and C/Wed to date. Post maint. run up indicates all op,s			
		normal	and no leaks noted at this time.			
	*	has bee	y this Propeller has been inspected IAW a ANNUAL inspection and an determined to be in an airworthy condition.			
		_	Lennie John Guerin 21483690 A/P IA			
		_	•			

DATE	TSN	TSO	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
9/4/			This propeller has been dynamically balanced using a
214/18	1		Chadwick Helmuth Vibrex Balance System I.P.S. Before
			I.P.S. After 💶 Weight added:
			grams.
			Authorized Signature 7 1 17 4 7 7 6 13 7 6 13
			2/1/18
			EGA Aviation, Inc. 2642 Airport Dr.
			N. Las Vegas, NV. 89032 (702) 683-7507
			N8SR
			Keinstalled due to engine change MT propeller prior removed. Installed with
			new "O" ring and torqued IAW MT torque spec,s. Painted propeller face and reinstalled and secured spinner. All AD,s checked and C/Wed to date. Post
			install run indicates all op,s normal and no leaks noted at this time.
			Aircraft returned to service Lennie John Guerin 21483690 A/P IA
			do-filker
			ECA Aulablan Tan
			EGA Aviation, Inc. 2642 Airport Dr.
			N. Las Vegas, NV. 89032 (702) 683-7507 N8SR /05-8 Propeller Logbook 1 June 2019
			Tach:1423.7 MTV-12-D WO#4064 S/N 120012 TSU02219
			C/W ANNUAL insp. IAW Piper PA-28R-201T checklist and MM. Removed spinner inspected prop mounting bolts. Dressed and painted prop. Inspect
			date. Post maintenance run up indicates all op,s normal and no leaks noted
		ļ. —	at this time.  Post maint. run up indicates all op,s normal and no leaks noted at this time.
	.1 22		I certify this PROPELLER has been insp. IAW a ANNUAL insp. and has been
	2		determined to be in an airworthy condition.
- e 3	537		Lennie John Guerip 21483690 A/P IA
Sing 8	10 0		
Š	1 3	<i></i>	de-prince
_ a	e de	)	
	weight added:		
<u></u>	いまり		
nica	W 4 3	5	*
nar A	12		EGA Aviation, Inc. 2642 Airport Dr.
<u></u> — € §	0 10	.—	1/5.1 N. Las Vegas, NV. 89032 (702) 683-7507 Received Level Association (1992)
Se e	i je o		NBRS PTJ. Propeller Logbook
las luth	P.S. After	)	Tachiseee 20034C312 W084181 3/11 13/01 13/
	Sign		Piper PA-20R-2011 Mr. records. Form 337 porvided. Post installation run up indicates all
— je 4	I.P.S Zed S	_	op,s normal and no leaks noted at this time.
P Pro		s	Aircraft returned to service Lennie John Guerin 1483090 A/P IA
This propeller has been dynamically balanced using a	Sgrams. Authorized Signature:		Dem Diver

P	ac	10	No.
	ay	10	140.

			DECODIDATION OF WORK DEDECORATE			
DATE	TSN	TSO DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK				
1/1/19	1585		INSTALL PROP GUARO PAFLE19359-1 05-	05335		
			I.AW STC SPOOS82NY	Í		
			0 614			
			1 (then)			
			276965 ATP			
	)	1	,			
		EGA Aviation, Inc. 2642 Airport Dr. Las Vegas, NV. 89032 (702) 683-7507 NBSR PHCCSYF-IRF Propeller Logbook QG/7/5/3 24 July 2020 Tach:0200.5 Z4DM6-666 W034486 S/N 615635 TTSO: 0085.4 C/W ANNUAL insp. IAW piper PA-28R-2017 checklist and MM. Removed spinner and inspected prop mounting hardware with no defects noted. Reinstalled spinner and secured. All AD,s checked and C/Wed to date. Post maintenance run up indicates all op,s normal and no defects or leaks noted.  I certify this PROPELLER has been insp. IAW a ANNUAL insp. and has been determined to be in an airworthy condition.  Lennie John Guerin 21483690 A/P IA				
			EGA Aviation, Inc. 2642 Airport Dr. N. Las Vegas, Nv. 89032 (702) 683-7507			
		N8SR	Propeller Logbook 01 Aug 2021			
	,,		PHC-C3YF-1RF WO#4763 S/N: QG1715B TTSN: 142.5			
		Inspected prop. Reinst	al inspection IAW Piper PA-28R-201T checklist and MM. Removed spinner.  fopeliler mounting hardware with no defects noted. Dressed and painted allied and secured spinner. All AD's checked and C/W to date. Post Maint. run all ops normal and no leaks noted. No inop equipment			
			Propeller has been insp. IAW an annual insp. and has been			
		determined t	to be in an airworthy condition.			
			•			
			James Catchings 2769658 A/P I/A			
			· SCately -			
			- Cure -			
			1			
	-					
			· ·			