



*The Standard*

# PROPELLER LOG

ASA-SP-1

**Propeller Record** General Information

Propeller Manufacturer Hartzell  
Model HC-C39R-1RF Type F7282  
Hub Series # DY5891B Blade # J91373  
Date of Manufacture \_\_\_\_\_ J91408  
J91412

**Make/Model**

**Serial #**

Aircraft Installed On: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____	Total Time in S
Date: _____	
Next Inspection Due: _____	Time Overhaul
Year: _____	Total in S
Date: _____	
Next Inspection Due: _____	Time Overhaul
Year: _____	Total in S
Date: _____	
Next Inspection Due: _____	Time Since Overhaul



Make HARTZELL Model HC-C3YR-1RF  
Serial Number DY5891B

The propeller identified above has been  
**REPAIRED/OVERHAULED/INSPECTED**

In accordance with manual 113B  
and is approved for return to service.  
Details on file under work order and 8130-3 number 9309

Signature  Date 22/OCT/2020  
Fosters Propeller Service Inc. Repair Station F3PR014N  
26650 Hwy 62 Boynton, OK 74422 Ph. 918-733-2131

FOSTERPROPELLER@WINDSTREAM.NET FOSTERSPROPELLER.COM


Mech. Cert. # or Repair Station # \_\_\_\_\_

**HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

**PROPELLER- N56790 S/N:DY5891B MAKE/MODEL: HC-C3YR-1RF**

DATE: 02/04/2021 FLIGHT TACH: 4973.0

I certify this propeller has been inspected with an annual inspection and found to be in an airworthy condition. Accomplished a satisfactory ground operational test. I certify that the maintenance described above was accomplished in accordance with the manufacturer's maintenance program, requirements of 14 CFR 43, and with respect to the work performed is airworthy and approved for return to service.

  
\_\_\_\_\_ Jeremy Fortier AP 3226880 IA

**PROPELLER- N56790 S/N:DY5891B MAKE/MODEL: HC-C3YR-1RF**

DATE: 01/18/2022 FLIGHT TACH: 5070.3

I certify this propeller has been inspected with an annual inspection and found to be in an airworthy condition. Accomplished a satisfactory ground operational test. I certify that the maintenance described above was accomplished in accordance with the manufacturer's maintenance program, requirements of 14 CFR 43, and with respect to the work performed is airworthy and approved for return to service.

  
\_\_\_\_\_ Jeremy Fortier AP 3226880 IA

Mech. Cert. # or Repair Station # \_\_\_\_\_

I

PROP MODEL:  
HC-C3YR-1RF  
PROP SN: DY5891B  
REG. NO. N56790  
WORK ORDER:  
0592-07-2022



**GoldStrike Aircraft Services**

2705 Airport Dr  
North Las Vegas, NV 89032  
Phone: (702) 899-1150

DATE: 8/4/2022  
A/C TSN: 5171.7  
PROP TT: 5171.7  
TSPOH: 199.4  
TACH: 5171.7

Year

Date

**Prop Entries**

Next

Due

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

The aircraft and/or component(s) on N56790 was repaired and inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details are on file at this facility under the above W.O. number.

Year

Date

DATE: 8/4/2022

SIGNED:

Mark Blackwood, A&P: 4484732

Work Order: 0592-07-2022

Printed by EBis 3 (datcomedia.com)

Next

Due

PROP MODEL:  
HC-C3YR-1RF  
PROP SN: DY5891B  
REG. NO. N56790  
WORK ORDER:  
0797-12-2022



**GoldStrike Aircraft Services**

2705 Airport Dr  
North Las Vegas, NV 89032  
Phone: (702) 899-1150

DATE: 1/12/2023  
A/C TSN: 5272.7  
PROP TT: 5272.7  
TSPOH: 300.4  
TACH: 5272.7

Year

Date

**Prop Entries**

I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.

The aircraft and/or component(s) on N56790 was repaired and inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details are on file at this facility under the above W.O. number.

Next

Due

DATE: 1/12/2023

SIGNED:

Mark Blackwood, A&P: 4484732

Work Order: 0797-12-2022

Printed by EBis 3 (datcomedia.com)