



# PROPELLER

## MAINTENANCE RECORDS

Logbook # 3

Provided Courtesy of:



DATE	TOTAL TIME IN SERVICE	TACH OR HOBBS METER TIME	DESCRIPTION OF WORK/SERVICES PERFORMED SIGNATURE & CERTIFICATE # OF PERSON PERFORMING WORK
TOTAL TIME FORWARDED FROM PREVIOUS PAGE			
	PROP MODEL: 3A32C76-SMAOIS-82NB-2 PROP S/N: 756649 REG NO: N8393S WORK ORDER: 0556-06-2022	 <b>GoldStrike Aircraft Services</b> 2705 Airport Dr North Las Vegas, NV 89032 Phone: (702) 899-1150	DATE: 9/1/2022 A/C TSN: 2826 PROP TT: 1356 TSPOH: 705.6 TACH: 2826
<b>Prop Entries</b>			
I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.			
The aircraft and/or component(s) on N8393S was repaired and inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details are on file at this facility under the above W.O. number.			
DATE: 9/1/2022		SIGNED: 	Work Order: 0556-06-2022
		Mark Blackwood, A&P-4484732	Printed by EBis 3 (datcomedia.com)
TOTAL TIME - CARRIED FORWARD TO NEXT PAGE			