

LICENCE:
AME or
AMO/ACAPROP MODEL (S)
MTV-6-R-C-F
PROP BN (S) 180774
REG. NO. 1815W
WORK ORDER
10019-10-2022Premier Aircraft Service, Inc.
3540 HWY 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393DATE: 1/17/2022
A/C TSN: 382 Z
PROP TT (S): 382 Z
TACH: 382 Z**Left Prop Entries**

(5) CAV ANNUAL INSPECTION ON THIS LH PROPELLER IAW 14 CFR PART 43, APPENDIX "D" USING MT-PROPELLER E-124 MM INSPECTION CHECKLIST AS A GUIDE. ADE CHECKED THROUGH CURRENT ON ATP.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 1/17/2022

SIGNED:

Work Order: 9635-12-2021

EMMANUEL VICIOSO
CRS 9PRR402B

Printed by EBis 3 (datamedia.com)

PROP MODEL (S)
MTV-6-R-C-F
PROP BN (S) 180774
REG. NO. 1815W
WORK ORDER
10019-10-2022Premier Aircraft Service, Inc.
3540 HWY 23rd Avenue Hangar 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393DATE: 1/14/2022
A/C TSN: 464
PROP TT (S): 453 Z
TACH: 464**Left Prop Entries**

(5) CAV ANNUAL INSPECTION ON THIS LEFT PROPELLER IAW 14 CFR PART 43, APPENDIX "D" USING MT-PROP E-124 MM INSPECTION CHECKLIST AS A GUIDE. ADE CHECKED THROUGH CURRENT ON ATP.

I CERTIFY THIS AIRFRAME, ENGINE, OR PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

DATE: 1/14/2022

SIGNED:

Work Order: 10019-10-2022

EMMANUEL VICIOSO
CRS 9PRR402B

Printed by EBis 3 (datamedia.com)

AMERITECH INDUSTRIES DBA
AMERICAN PROPELLER SERVICE
REPAIR STATION NO. N03R717L
2020B CHARLANNIE DRIVE
REDDING, CA 96002 USA

WORK ACCOMPLISHED

*Overhauled*MODEL NO. *MTV-6-R-C-F*SERIAL NO. *180774*

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER

REPAIR ORDER # *28110-02-2024*DATED: *03-18-2024*

SIGNED:

MIKE CROWELL

(AUTHORIZED INDIVIDUAL)

FORM LB01